

March 13, 2024

Rick Underwood  
Director of Operations & Maintenance  
Lowell Public Schools  
155 Merrimack Street, 4<sup>th</sup> Floor  
Lowell, Massachusetts 01852

via email: [runderwood@lowell.k12.ma.us](mailto:runderwood@lowell.k12.ma.us)

**RE: AHERA 3-Year Reinspection  
Cardinal O'Connell Early Learning Center  
21 Carter Street  
Lowell, Massachusetts  
EFI Project No. 014.07795**

Dear Mr. Underwood:

EFI Global Inc. (EFI) is pleased to present this AHERA 3-Year Reinspection Report prepared for the Cardinal O'Connell Early Learning Center located at 21 Carter Street, Lowell, Massachusetts (Site). The reinspection site visit was conducted on February 21, 2024, and the corresponding report was completed in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) regulations (40 CFR 763) and Massachusetts Department of Labor Standards "Requirements for Schools Subject to AHERA" regulations (454 CMR 28.13).

EFI relied upon previous 3-Year Inspection and Management Plan Update report from 2014 prepared by Cardo ATC, and 2017 and 2020 reinspection's prepared by EFI Global Inc. The original AHERA Management Plan and other subsequent records were not made available at the school for review. EFI relied upon the 2020 table of identified ACM for this reinspection. The school's Management Plan and records should be located and kept on file at the school and the administrative offices.

EFI is pleased to provide environmental consulting services to Lowell Public Schools. This report should be kept on file with the school's AHERA records. If you have any questions regarding the contents of this report, or are in need of additional information, please contact either of the undersigned at (800) 659-1202. Thank you for the opportunity to serve your environmental needs.

Sincerely,  
**EFI Global, Inc.**



Derrick Calvario  
Project Manager  
MA Asbestos Inspector # AI 900703



Michael McCarter  
Senior Project Manager  
MA Asbestos Management Planner #AP 035661

## **AHERA 3-YEAR REINSPECTION**

**FOR:**

**CARDINAL O'CONNELL EARLY LEARNING CENTER  
21 CARTER STREET  
LOWELL, MASSACHUSETTS**

**PREPARED BY:**



**155 WEST STREET, SUITE 6  
WILMINGTON, MASSACHUSETTS 01887**

**EFI PROJECT NUMBER 014.07795**

**March 13, 2024**

## TABLE OF CONTENTS

<b>INTRODUCTION.....</b>	<b>1</b>
<b>AHERA 3-YEAR REINSPECTION.....</b>	<b>2</b>
A. AHERA Records Review.....	2
B. ACM Application Types.....	3
C. ACM Assessment Criteria.....	3
D. Response Actions – General Recommendations.....	5
E. AHERA Licensing & Training Documentation.....	5
F. Asbestos Bulk Sampling.....	6
G. ACM Hazard Assessment and Recommended Response Actions.....	7
H. Cost Estimate for Recommended Response Actions.....	7

### Attachments:

Attachment A – AHERA Summary Table of ACMs and Recommended Response Actions

Attachment B – Site Plans and 2024 Reinspection Bulk Sample Locations

Attachment C –2024 Reinspection Asbestos Bulk Sample Laboratory Report

Attachment D – Licenses and Training Certificates of Asbestos Inspector and Management Planner

## **INTRODUCTION**

EFI Global, Inc. (EFI) was retained by Lowell Public Schools to perform a 3-Year AHERA Reinspection in accordance with United States Environmental Protection (USEPA) Asbestos Hazard Emergency Response Act (AHERA) asbestos regulations (40 CFR 763) and Massachusetts Department of Labor Standards “Requirements for Schools Subject to AHERA” regulations (454 CMR 28.13). These regulations, commonly known as the “Asbestos in Schools Rule,” require under 40 CFR 763.80 and 454 CMR 28.13(2)(b)(1) that local education agencies (LEAs) must conduct a reinspection at least once every three years of all friable and nonfriable known or assumed asbestos-containing materials (ACMs). The reinspection includes all previously known and assumed ACMs, as well as any additional suspect ACM not previously included, as required by 40 CFR 763.80 and 454 CMR 28.13 in each school building leased, owned, or otherwise used as a school building. A school building is defined in 454 CMR 28.02 as including each of the following:

- Any structure suitable for use as a classroom, including a school facility such as a library, school eating facility, or facility used in the preparation of food
- Any gymnasium or other facility which is specially designed for athletic or recreational activities for an academic course in physical education
- Any other facility used for the instruction or housing of students or for the administration of educational or research programs
- Any maintenance, storage, or utility facility, including any hallway, essential to the operation of any facility described as a school building above
- Any portico or covered exterior hallway or walkway
- Any exterior portion of a mechanical system used to condition interior space.

EFI conducted a 3-year AHERA re-inspection at the Cardinal O’Connell Early Learning Center, which involved determining the condition and hazard potential of previously known and assumed ACMs, and additional confirmed and assumed ACMs observed during the 2024 reinspection. The 3-year re-inspection was conducted on February 20, 2024, by Derrick Calvario and Emma Cypherd, both EPA accredited, and Massachusetts Department of Labor Standards (MADLS) licensed Asbestos Inspectors, (license number AI-900703) and (license number AI-901189) respectively. EFI relied upon the 2020 3-year reinspection table of identified and assumed ACMs for this reinspection. The original AHERA Management Plan and subsequent records were not made available at the school for review. The recommended response actions were prepared by MADLS-licensed Asbestos Management Planner Michael McCarter (AP-033118).

A summary of known and assumed ACM within the Cardinal O’Connell Early Learning Center is presented in the AHERA Summary Table in **Attachment A**. Site Plans showing buildings and locations referenced in this report are presented in **Attachment B**.

The Designated Person for the Lowell Public Schools is Rick Underwood. Rick’s contact information is:

Rick Underwood  
Director of Operations & Maintenance  
Lowell Public Schools  
155 Merrimack Street, 4<sup>th</sup> Floor  
Lowell, Massachusetts 01852  
978-674-4328  
[runderwood@lowell.k12.ma.us](mailto:runderwood@lowell.k12.ma.us)

**AHERA 3-YEAR REINSPECTION****A. AHERA Records Review**

As part of this 3-year reinspection, EFI reviewed available AHERA records for the school, in accordance with the AHERA regulation and 454 CMR 28.13(5)(f). A summary of records reviewed is provided in the table below.

<b>Review of AHERA Documentation</b> <b>Cardinal O'Connell Early Learning Center</b> <b>21 Carter Street, Lowell, Massachusetts</b>		
<b>Document/Record</b>	<b>Present?</b>	<b>Comment</b>
Asbestos Management Plan (on hand at school and available for review)	No	No records available at the school for review. The Cardo ATC 2014 3-Year Reinspection and Updated Management Plan is posted on the school web site.
Designated Person Training Records (for Rick Underwood)	No	No records available at the school for review. Designated Person should receive formal designated person training or review the Designated Person Self Study Guide (available at <a href="https://www.epa.gov/sites/default/files/2015-01/documents/dp_study_guide_0.pdf">https://www.epa.gov/sites/default/files/2015-01/documents/dp_study_guide_0.pdf</a> ).
Custodial Personnel 2-hour Awareness Training Records	No	No records available at the school for review.
Annual Parental Notification Records	No	No records available at the school for review. Annual notification letters should be sent and copies kept on file with the AHERA records.
Abatement/Response Action Records (includes abatement, special cleaning activities & small scale short duration (SSSD) activities and associated monitoring reports and work plans)	No	No records available at the school for review.
Designated Person True and Correct Statement	No	No records available at the school for review.
6-month Surveillance Inspection Records	No	No records available at the school for review.
Previous 3-Year Reinspection Records	No	No records available at the school for review.
Asbestos Labels present (required in routine maintenance areas)	No	No labeling observed. Labels should be placed immediately adjacent to ACM present in routine maintenance areas (i.e., boiler rooms, utility closets, etc.)

## **B. ACM Application Types**

ACMs are divided into the following application types:

Thermal system insulation (TSI): Insulation applied to mechanical, heating, and cooling systems such as pipes, boilers, flue breechings, ducts, tanks and fittings.

Surfacing Materials: Material that is spray-applied or trowel-applied to walls, ceilings or structural components (i.e. plasters, acoustical finishes and fireproofing).

Miscellaneous Materials: All other asbestos materials, including but not limited to floor tiles and mastic, ceiling tiles, vinyl cove base and mastic, gypsum board and joint compound, and asbestos-cement board, etc.

## **C. ACM Assessment Criteria**

The assessment is divided into two categories - the physical assessment and the hazard potential assessment.

### Physical Assessment

The physical assessment is divided into the following seven categories and describes the material condition at the time of the inspection:

- Physical Condition #1 - Damaged or significantly damaged thermal system ACM.
- Physical Condition #2 - Damaged friable surfacing ACM.
- Physical Condition #3 - Significantly damaged friable surfacing ACM.
- Physical Condition #4 - Damaged or significantly damaged miscellaneous ACM.
- Physical Condition #5 - ACM with potential for damage.
- Physical Condition #6 - ACM with potential for significant damage.
- Physical Condition #7 - Any remaining friable ACM or friable suspected ACM.

### Hazard Assessment

The hazard assessment is a combination of the physical assessment combined with the potential for disturbance (i.e., physical contact, vibration air movement) as follows:

- Hazard Rank #1 – Good condition/Low potential for disturbance
- Hazard Rank #2 – Good condition/ Moderate potential for disturbance
- Hazard Rank #3 – Good condition/ High potential for disturbance
- Hazard Rank #4 – Damaged condition/Low potential for disturbance
- Hazard Rank #5 – Damaged condition/Moderate potential for disturbance
- Hazard Rank #6 – Damaged condition/High potential for disturbance
- Hazard Rank #7 – Significantly damaged condition

The following is the Assessment Criteria used during the inspection:

1. Homogeneous Areas (An area of surfacing material, thermal system insulation material, or miscellaneous material that is uniform in size, color and texture and was applied at approximately the same time) were quantified by location and assessed by condition. Materials are listed as friable or non-friable. Note: friable materials are materials that can be crushed and pulverized to dust by hand pressure. A general condition description for suspect materials used in this inspection is as follows:
  - a. Damaged Surfacing ACM: That material which has deterioration, delamination, water damage, lacks cohesion, is blistered, crumbling, gouged, marred heavily, abraded, or in any way has lost its structural integrity over more than 1% but less than 10 % of the total surface area if the damage is evenly distributed or less than 25%, if the damage is localized in one area of the homogeneous area.
  - b. Significantly Damaged ACM: That material which has deterioration, delamination, water damage, lacks cohesion, is blistered, crumbling, gouged, marred heavily, abraded, or in any way has lost its structural integrity over at least 10% of the surface area if the damage is evenly distributed or at least 25% if the damaged is localized.
  - c. Good Condition ACM: ACM with no visible damage or deterioration in less than one percent of the material and/or coverings.
  - d. ACM with potential for damage: Pertains to circumstances in which:
    - i. Friable ACM is in an area regularly used by building occupants, including maintenance workers, currently in intact (good) condition.
    - ii. There are indications that there is a reasonable likelihood that the material or its covering will become damaged, deteriorated or delaminated due to factors such as changes in building use, changes in O&M practices, changes in occupancy or recurrent damage.

Note: All ACM in good condition is still considered to have a potential for damage, and in certain instances, has the potential for significant damage.

- e. ACM with potential for significant damage: Pertains to circumstances in which:
  - i. Friable ACM is in an area regularly used by building occupants, including maintenance personnel.
  - ii. Indications show that there is a reasonable likelihood that the material or its covering will become damaged, deteriorated, or delaminated due to factors such as changes in building use, changes in O&M practices, changes in occupancy or re-occurring damage.
  - iii. The material is subject to major or continuing disturbance, due to factors including, but not limited to, accessibility or under certain circumstances, vibration or air erosion.

**D. Response Actions – General Recommendations**

Specific response actions for each known and assumed ACM located at the Cardinal O’Connell Early Learning Center are located in **Attachment A**. The following are general recommendations for response actions associated with managing ACMs at the school.

1. Damaged materials in the school should be repaired, if feasible, or removed in order to maintain compliance with the AHERA regulations. Damaged ACMs of any quantity listed in the report should be repaired or removed by a Massachusetts licensed asbestos abatement contractor following all applicable regulations, in accordance with a work plan design, and final clearance air testing performed in accordance with the AHERA regulations. It is the policy of the Lowell Public Schools to use licensed asbestos contractors for all response action work.
2. The AHERA regulation states that the response actions chosen for other than small scale/short duration repairs (less than 3 square or linear feet), must be designed and conducted by persons accredited to design and conduct response actions. MADLS Regulation 454 CMR 28.00 requires the services of licensed Project Designers who meet the requirements set forth in 454 CMR 28.00, as well as Massachusetts licensed Asbestos Contractors.
3. Damaged ACMs that involve small scale/short duration repairs can only be conducted by 16-hour asbestos-trained personnel or by a licensed Asbestos Contractor. EFI understands that small scale/ short duration projects will not be performed by in house personnel, and that all work will be conducted by an outside licensed Asbestos Contractor.
4. Each known and assumed ACM should be monitored for any changes in condition during the six-month periodic surveillance, or more frequently.
5. If known or suspect ACMs are to be impacted by planned renovation or demolition activities, the ACM must be removed by a Massachusetts licensed Asbestos Contractor. Note that AHERA inspections do not meet the EPA NESHAP and Commonwealth of Massachusetts Department of Environmental Protection (MADEP) requirements for a comprehensive pre-renovation or demolition survey. Prior to any planned renovation or demolition project, all renovation/demolition areas must be thoroughly surveyed to meet the requirements of EPA NESHAP and MADEP 310 CMR 7.15(4) Survey Requirements. LEA Designated Persons should make sure that pre-renovation/demolition surveys are performed in each instance that ACM may be disturbed.

**E. AHERA Licensing & Training Documentation**

The AHERA 3-year Reinspection report for the Cardinal O’Connell Early Learning Center was performed by the following individuals who have received appropriate training and who are MADLS licensed personnel:



Derrick Calvario  
Project Manager  
MA Asbestos Inspector # AI 900703



Michael McCarter  
Senior Project Manager  
MA Asbestos Management Planner #AP 035661



## F. Asbestos Bulk Sampling

Asbestos bulk sampling of suspect ACM was performed for various suspect ACMs not previously identified as ACM in portions of the building included in the AHERA program. The bulk sampling was performed by USEPA-accredited, and MADLS licensed Asbestos Inspector Derrick Calvario and Emma Cypherd. A total of 33 bulk samples of suspect ACMs were collected and transported under chain of custody protocol to EMSL Analytical, Inc., of Woburn, Massachusetts, a Massachusetts-licensed laboratory. EMSL is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for bulk asbestos fiber analysis, which is administered by the National Institute of Standards and Testing (NIST).

Samples were analyzed with a standard 3-day turnaround time using polarized light microscopy (PLM) in accordance with United States Environmental Protection Agency (USEPA) Method 600/R-93/116. The PLM/DS analytical method is modeled after 40 CFR Part 763, Subpart F, Attachment A: "Interim Method for the Determination of Asbestos in Bulk Insulation Samples." MADEP asbestos regulations define an ACM as any material containing greater than or equal to one percent asbestos. The findings of this report are based upon observations of accessible materials and the analysis of representative bulk samples collected. **Attachment B** contains site plans indicating locations of samples collected and analyzed as part of this reinspection. A copy of the asbestos laboratory reports is presented in **Attachment C**.

Bulk samples representing individual homogenous areas of suspect ACM, (materials that are determined to be uniform in color and texture and installed in the same construction period) were collected in a randomly distributed manner, in accordance with the EPA sampling protocol outlined in 40 CFR 763.

The following suspect ACMs sampled by EFI during the 2024 reinspection were reported by EMSL as containing no detectable concentration of asbestos:

### Summary of Non-ACMs per 2024 3-Year Reinspection

Material Description	Location(s) Sampled
1' X 1' White Floor Tile	Basement CFCE Area
Yellow Mastic Associated with 1' X 1' White Floor Tile	Basement CFCE Area
2' X 4' Pinhole Ceiling Tile	3 <sup>rd</sup> /4 <sup>th</sup> Floor Staircase, Basement Hallways
Yellow Carpet Mastic	Main Office 2 <sup>nd</sup> Floor
Ceramic Tile Grout	2 <sup>nd</sup> Floor Hallway
Gypsum Board*	Basement Hall, 3 <sup>rd</sup> Floor Offices
Base Coat Plaster*	Basement Left Stair, Principals Office, 2 <sup>nd</sup> Floor Main Hallway, 3 <sup>rd</sup> Floor Stair Right, 3 <sup>rd</sup> Floor Faculty Room, 3 <sup>rd</sup> Floor Offices, 3 <sup>rd</sup> Floor Stair Case Ceiling

\* EFI recommends that the material be treated and disposed of as an ACM since the associated ACM cannot be easily separated (associated ACM is listed in the AHERA 3-year reinspection table contained in Attachment A).

## G. ACM Hazard Assessment & Recommended Response Actions

Accessible locations were inspected and assessed to determine the presence and condition of ACM. A Summary Table of known and assumed ACMs present at the school, the physical and hazard assessments and the recommended response action for each ACM, is presented in **Attachment A**. It should be noted that EFI did not conduct destructive evaluations of the school building to identify suspect ACM. Per USEPA NESHAP and MADEP asbestos regulations, a thorough “path of construction” survey should be conducted prior to any renovation or repair activities that may impact suspect ACM, regardless of the date of installation.

## H. Cost Estimate and Schedule for Recommended Response Actions

The confirmed and assumed ACMs outlined in the summary table in **Attachment A** that were in good condition at the time of the reinspection must be maintained in place in accordance with the Operations and Maintenance Plan. Estimated costs associated with managing known and assumed ACMs at the school are summarized below.

Cost Estimate of AHERA Considerations Cardinal O’Connell Early Learning Center 21 Carter Street, Lowell, Massachusetts	
Training Costs	
Item	Approximate Cost
2-hour asbestos awareness training (New Hires, within 60 days of hire)	\$500/person
Designated Person Training	\$250
Maintenance Costs	
Item	Approximate Cost
Asbestos labeling (Place/maintain labels adjacent to ACM in routine maintenance areas)	\$500
6-month surveillance inspections (Per schedule below)	\$500/event
3-year re-inspection (Per schedule below)	\$2,000
Response Action Costs	
Item	Approximate Cost
Immediately and annually notify occupants regarding ACM materials noted in the Summary Table if Identified and Assumed ACMs.	\$500
2’ x 4’ Large fissured ceiling tile – Perform initial cleaning as recommended in the Summary Table if Identified and Assumed ACMs.	\$10,000

A proposed schedule of events between this 3-Year reinspection and the 2027 3-Year reinspection is provided for your use:

<b>Schedule of AHERA-Related Actions</b> <b>Cardinal O'Connell Early Learning Center</b> <b>21 Carter Street, Lowell, Massachusetts</b>	
<b>Event</b>	<b>Completion Date</b>
Immediately and annually notify occupants regarding ACM ceiling tile, plaster skim coat, and joint compound as recommended in the Summary Table of Identified and Assumed ACMs.	By February 20 <sup>th</sup> , 2024, and annually thereafter.
2' x 4' Large fissured ceiling tile – Perform initial cleaning as recommended in the Summary Table of Identified and Assumed ACMs.	By February 20 <sup>th</sup> , 2024, and annually thereafter. Perform initial cleaning by June 30 <sup>th</sup> , 2024
6 Month Surveillance Inspection	August 20, 2024
Annual Parental Notification Letter	September 1, 2024
6 Month Surveillance Inspection	February 20, 2025
6 Month Surveillance Inspection	August, 2025
Annual Parental Notification Letter	September 1, 2025
6 Month Surveillance Inspection	February 20, 2026
6 Month Surveillance Inspection	August 20, 2026
Annual Parental Notification Letter	September 1, 2026
3 Year Reinspection	February 20, 2027

**ATTACHMENT A**

**AHERA SUMMARY TABLE**

AHERA 3-Year Reinspection Summary Table  
Cardinal O’Connell Alternative School  
Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
21 Carter Street, Lowell, MA  
Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
1	Pipe Insulation on Boiler Exhaust	Basement – Boiler Room	40 LF	NF	Not Sampled. Assumed ACM	6	Good	Manage in place in accordance with the Asbestos O&M Program. Rooms where vibration is present due to operating mechanical equipment can be inspected regularly for damage, such as every three months by trained maintenance personnel.	
2	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - Boiler Room	500 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O& Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	
3	“Aircell” Pipe Insulation	Basement – Hallway by Custodian’s Office	4 LF	NF	Not Sampled. Assumed ACM	6	Good	Manage in place in accordance with the Asbestos O&M Program. Pipe insulation in a hallway that is readily accessible to occupants can be inspected regularly for damage, such as every three months by trained maintenance personnel.	
4	Pipe Fitting Insulation	Basement – Storage Room Near Custodian’s Office	2 Elbows	NF	Not Sampled Assumed ACM	6	Good	Manage in place in accordance with the Asbestos O&M Program. Do not store ladders, supplies or other equipment near the pipe fitting insulation.	
5	2’ x 4’ Large Fissure Ceiling Tile (material added per 2024 reinspection)	Basement - Hallways	250 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024
6	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - Hallways	1000 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
7	2’ x 4’ Large Fissure Ceiling Tile (material added per 2024 reinspection)	Basement - SW Office	250 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024

AHERA 3-Year Reinspection Summary Table  
 Cardinal O’Connell Alternative School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 21 Carter Street, Lowell, MA  
 Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
8	Joint Compound Walls (material added per 2024 reinspection)	Basement - SW Office	600 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
9	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - SW Office	200 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
10	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	Basement - SW Office Closet	100 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024
11	Joint Compound on Walls (material added per 2024 reinspection)	Basement - Custodian	800 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
12	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - Custodian	300 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
13	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	Basement - CFCE	500 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024

AHERA 3-Year Reinspection Summary Table  
Cardinal O’Connell Alternative School  
Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
21 Carter Street, Lowell, MA  
Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
14	Joint Compound on Walls (material added per 2024 reinspection)	Basement - CFCE	1000 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
15	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - CFCE	425 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
16	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	Basement - Conference Room	350 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024
17	Joint Compound on Walls (material added per 2024 reinspection)	Basement - Conference Room	750 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
18	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - Conference Room	250 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
19	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	Basement - Gym	600 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024

AHERA 3-Year Reinspection Summary Table  
 Cardinal O’Connell Alternative School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 21 Carter Street, Lowell, MA  
 Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
20	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - Gym	700 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
21	Joint Compound on Walls (material added per 2024 reinspection)	Basement Hallway off Gym	300 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
22	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	Basement - Rear Storage Areas	300 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024
23	Joint Compound on Walls (material added per 2024 reinspection)	Basement - Rear Storage Areas	250 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
24	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - Rear Storage Areas	950 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
25	Joint Compound on Walls (material added per 2024 reinspection)	Basement - Girl's Bathroom	150 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.



AHERA 3-Year Reinspection Summary Table  
 Cardinal O’Connell Alternative School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 21 Carter Street, Lowell, MA  
 Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
26	Plaster Skim Coat on Ceilings (material added per 2024 reinspection)	Basement - Girl's Bathroom	250 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
27	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Principal's Office	450 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024
28	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Principal's Office	250 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
29	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	1 <sup>st</sup> Floor Hallway/ Staircase	500 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024
30	Joint Compound on Walls (material added in 2024)	1 <sup>st</sup> Floor - Hallway/ staircase	500 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
31	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor Hallway/ Staircase	1300 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.

AHERA 3-Year Reinspection Summary Table  
Cardinal O’Connell Alternative School  
Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
21 Carter Street, Lowell, MA  
Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
32	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor Hallway/ Staircase	1300 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
33	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Room 1	1150 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
34	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Main Office	1100 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
35	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Main Office Bathroom	250 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
36	Floor Tile	1 <sup>st</sup> Floor – Bathroom in Main Office	15 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	Notify by February 20, 2024, and annually thereafter.
37	Mastic associated with Floor Tile	1 <sup>st</sup> Floor – Bathroom in Main Office	15 SF	NF	Positive per Management Plan records	N/A	NA, not visible for inspection	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program.	
38	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Room 2	800 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
39	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Room 3	800 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.

AHERA 3-Year Reinspection Summary Table  
 Cardinal O’Connell Alternative School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 21 Carter Street, Lowell, MA  
 Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
40	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Room 4	1000 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
41	Joint Compound on Walls (material added per 2024 reinspection)	1 <sup>st</sup> Floor - Room 4	200 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
68	2' x 4' Large Fissure Ceiling Tile (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Hallway/ Staircase	500 SF	F	2% Chrysotile Asbestos	5	Good	Immediately and annually thereafter notify occupants that the tiles are ACM and should not be disturbed by lifting or moving tile, hanging items from the ceiling tile grid or other activities. Perform an initial cleaning as required by 454 CMR 28(7)(b) that includes HEPA-vacuuming or steam-cleaning of carpets, and HEPA-vacuuming or wet cleaning of all floors and horizontal surfaces below ACM ceiling tiles. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter. Perform initial cleaning by June 30, 2024
69	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Hallway/ Staircase	1300 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
70	Joint Compound on Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Hallway/ Staircase	700 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
71	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Room 5	1000 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.

AHERA 3-Year Reinspection Summary Table  
 Cardinal O’Connell Alternative School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 21 Carter Street, Lowell, MA  
 Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
72	Joint Compound on Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Room 5	300 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
73	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Room 6	850 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
74	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Faculty/Staff Room	1100 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
75	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Faculty/Staff Bathroom	300 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
76	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Offices	650 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
77	Joint Compound on Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Offices	1000 SF	NF	2% Chrysotile Asbestos (note that associated gypsum board is non-ACM)	5	Good	Immediately and annually thereafter notify occupants of the ACM joint compound associated with gypsum board walls and ceilings and do not disturb the material by hanging items or storing materials against the joint compound. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.
78	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Room 7	1150 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.

AHERA 3-Year Reinspection Summary Table  
Cardinal O’Connell Alternative School  
Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
21 Carter Street, Lowell, MA  
Dates of Inspection: 2/21/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
79	Plaster Skim Coat on Ceiling and Walls (material added per 2024 reinspection)	2 <sup>nd</sup> Floor - Room 8	850 SF	NF	2% Chrysotile Asbestos (note that plaster base coat is non-ACM)	5	Good	Immediately and annually thereafter notify occupants that the plaster is ACM and should not be disturbed by hanging items or storing materials against plaster. Manage in place in accordance with the Asbestos O&M Program. Routine inspections of ACM for physical damages due to occupancy or other factors can be performed more frequently, such as every three months.	Notify by February 20, 2024, and annually thereafter.

SF = Square Feet

LF = Linear Feet

Assumed ACM = This material was not identified in the Management Plan records and was not sampled during the 2024 Re-inspection. Prior to any planned disturbance by maintenance, renovation, or demolition activities, EFI recommends bulk sampling and analysis to determine asbestos content.

For all recommended response actions, the work should be conducted by a Massachusetts licensed Asbestos Contractor and a work plan for the specific repair or removal activity should be prepared by a Massachusetts licensed Asbestos Designer.

Physical Assessment Category
1 – Damaged or Significantly Damaged Thermal System ACM
2 – Damaged Friable Surfacing ACM
3 – Significantly Damaged Surfacing ACM
4 – Damaged or Significantly Damaged Friable Miscellaneous ACM
5 – ACM with Potential for Damage
6 – ACM with Potential for Significant Damage
7 – Any Remaining friable ACM or friable suspect ACM

**ATTACHMENT B**

**SITE PLANS AND 2024 REINSPECTION ASBESTOS BULK SAMPLE LOCATIONS**

Primary route  
Secondary route


Carter St.  
Apts

Livingston

Carter Ave

Side D

Side B



Carter Ave  
C eps

Project Name	Small Public School
Project Status	Complete / Ongoing / Alternative Status
Address	311 Carter Ave Livingston, LA 70457


Park  
Barron



# Principal Office

Primary route Carter St.  
Secondary route

1st Floor Plan



Side A

Side D

Side B

Carter Ave  
Side C

Park  
1st Floor

Carter Ave

## Legend

- ① Electric Main
- ⊞ Transformer
- △ Generator
- ⊙ Water Main
- ⊖ Sprinkler Main
- ⊞ Gas Main
- ⊞ Oil Main
- ⊞ Camera
- ⊞ Chiller Unit
- ⊞ Ventr Box
- ⊞ Fire Alarm Control Panel
- ⊞ Fire Extinguisher
- ⊞ Fire Department Connection
- ⊞ Pump



District Name:	Lowell Public Schools
School Name:	Cardinal O'Connell Alternative School
Address:	21 Carter Street Lowell, MA 01852



Start Room

- Primary route

- Secondary route

Carter St.

Livingston St


Carter Ave.

Side B

Side D

Carter Ave

Side C



District Name:	Lowell Public Schools
School Name:	Cardinal O'Connell Alternative School
Address:	21 Carter Street Lowell, MA 01852

2nd Floor

- Legend
- Electric Main
  - Transformer
  - Generator
  - Water Main
  - Sprinkler Main
  - Gas Main
  - Oil Main
  - Steam Main
  - Fire Alarm Control Panel
  - Fire Extinguisher
  - Fire Department Connection

**ATTACHMENT C**

**2024 REINSPECTION ASBESTOS BULK SAMPLE LABORATORY REPORT**



# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com> / [bostonlab@emsl.com](mailto:bostonlab@emsl.com)

EMSL Order: 132401072

Customer ID: EAFI66

Customer PO:

Project ID:

Attention: Derrick Calvario

EFI Global, Inc.

155 West Street

Suite 6

Wilmington, MA 01887

Phone: (978) 688-3736

Fax: (978) 688-5494

Received Date: 02/23/2024 11:50 AM

Analysis Date: 02/26/2024 - 02/27/2024

Collected Date: 02/22/2024

Project: 014.07795 - Cardinal O'Connell School; Corner of Livingston Street & Carter Avenue

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
01A 132401072-0001	Basement CFCE Area - 12x12 White Floor Tile	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
01B 132401072-0002	Basement CFCE Area - 12x12 White Floor Tile	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
02A 132401072-0003	Basement CFCE Area - Yellow Tile Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
02B 132401072-0004	Basement CFCE Area - Yellow Tile Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
03A 132401072-0005	SW Office - 2x4 CT Large Fissure	Gray/White Fibrous Homogeneous	85% Min. Wool	13% Non-fibrous (Other)	2% Chrysotile
03B 132401072-0006	(1st Floor) Rear Basement Hallway - 2x4 CT Large Fissure				Positive Stop (Not Analyzed)
04A 132401072-0007	4th/3rd Floor Staircase - 2x4 CT Pinhole	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
04B 132401072-0008	(1st Floor) Basement Rear Hallway - 2x4 CT Pinhole	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
05A 132401072-0009	(1st Floor) Basement Hallway - Gypsum Board	Brown/Gray Fibrous Homogeneous	15% Cellulose 2% Glass	83% Non-fibrous (Other)	None Detected
05B 132401072-0010	3rd Floor Offices - Gypsum Board	Brown/White Fibrous Homogeneous	15% Cellulose	85% Non-fibrous (Other)	None Detected
06A 132401072-0011	2nd Floor - Joint Compound	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
06B 132401072-0012	Basement SW Office - Joint Compound	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
06C 132401072-0013	3rd Floor Offices - Joint Compound	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
06D 132401072-0014	Conf Room - Joint Compound	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
06E 132401072-0015	(1st Floor) Rear Basement Hallway Off Gym - Joint Compound	Tan Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
07A 132401072-0016	1st Floor/Basement Left Staircase - Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/27/2024 15:36:45





# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com/bostonlab@emsl.com>

EMSL Order: 132401072

Customer ID: EAFI66

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
07B 132401072-0017	Principal's Office - Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07C 132401072-0018	2nd Floor Main Hallway - Plaster Skim Coat	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
07D 132401072-0019	3rd Floor Staircase Right - Plaster Skim Coat	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
07E 132401072-0020	3rd Floor Faculty Room - Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07F 132401072-0021	3rd Floor Offices - Plaster Skim Coat	Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07G 132401072-0022	3rd Floor Staircase Ceiling - Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
08A 132401072-0023	1st Floor/Basement Left Staircase - Plaster Base Coat	White Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
08B 132401072-0024	Principal's Office - Plaster Base Coat	Gray/White Non-Fibrous Homogeneous	<1% Hair	100% Non-fibrous (Other)	None Detected
08C 132401072-0025	2nd Floor Main Hallway - Plaster Base Coat	White Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
08D 132401072-0026	3rd Floor Staircase Right - Plaster Base Coat	Gray Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
08E 132401072-0027	3rd Floor Faculty Room - Plaster Base Coat	Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
08F 132401072-0028	3rd Floor Offices - Plaster Base Coat	Gray/White Non-Fibrous Homogeneous	<1% Hair	100% Non-fibrous (Other)	None Detected
08G 132401072-0029	3rd Floor Staircase Ceiling - Plaster Base Coat	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09A 132401072-0030	Main Office 2nd Floor - Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09B 132401072-0031	Main Office 2nd Floor - Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
10A 132401072-0032	2nd Floor Hallway - Ceramic Tile Grout	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
10B 132401072-0033	2nd Floor Hallway - Ceramic Tile Grout	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/27/2024 15:36:45



## EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com> / [bostonlab@emsl.com](mailto:bostonlab@emsl.com)

EMSL Order: 132401072

Customer ID: EAFI66

Customer PO:

Project ID:

Analyst(s)

John McCarthy (32)

Steve Grise, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-139, VT AL998919, ME LB-0039

Initial report from: 02/27/2024 15:36:45



132401072

BOSTON NORTH

155 West Street | Suite 6 | Wilmington, MA 01887 | PHONE 978.688.3736 | FAX 978.688.5494 | FREE 800.659.1202

## BULK SAMPLE CHAIN OF CUSTODY FORM

Report to (Inspector Name):	Derrin Calvano	Bill To:	Accounts Payable
Company:	EFI Global, Inc.	Address:	Same
Address:	155 West Street Suite 6	City, State, Zip:	Same
City, State, Zip:	Wilmington, MA 01887	Telephone:	800-659-1202
Inspector Cell:	781-825-5012	Email:	US-EFIGlobal-BostonEnviroPC@efiglobal.com
<b>Project Information</b>			
Project No./ Description:	014.07795 - Cardinal O'Connell School		
Email Report to:	Derrin Calvano @efiglobal.com → Corner of Livingston and Carter Ave		
Alternate:	Lancaster, MA		
<b>Requested Turnaround Time:</b>			
<input type="checkbox"/> RUSH (6hr)	<input type="checkbox"/> 1 day (24hr)	<input type="checkbox"/> 2 day (48hr)	<input checked="" type="checkbox"/> 3 day (72hr)
<input type="checkbox"/> 5 day			
<b>Media and Methodology</b>			
Type of Analysis:	PLM		Check for Positive Stop: <input checked="" type="checkbox"/>
Notes:	Analyze all plaster and joint compound samples		Date Collected: 2/22/24

Sample ID	Type of Material	Location
01A	12x12 white tile	Basement C-CE area
01B	" "	" "
02A	Yellow tile mastic	" "
02B	" "	" "
03A	2x4 CT large fissure	Sw office
03B	" "	rear basement hallway (1st fl)
04A	2x4 CT Pinhole	Sw office 4th/3rd fl staircase
04B	" "	Basement rear hallway (1st fl)
05A	Gypsum board	Basement hallway (1st fl)
05B	" "	3rd fl offices

Total Number of Samples Submitted: 33

Samplers Name: Derrin Calvano

Samplers Signature: [Signature]

Relinquished By (Client): [Signature]

REC'D

EMSL-BOSTON

FEB 23 2024

Date:

2/23/24

Time:

Received By (Lab):

Wain [Signature]

Date:

Time:



Page 2 of 2

**ATTACHMENT D**

**LICENSES AND TRAINING CERTIFICATES OF ASBESTOS INSPECTOR & MANAGEMENT PLANNER**



March 13, 2024

Rick Underwood  
Director of Operations & Maintenance  
Lowell Public Schools  
155 Merrimack Street, 4<sup>th</sup> Floor  
Lowell, Massachusetts 01852

via email: [runderwood@lowell.k12.ma.us](mailto:runderwood@lowell.k12.ma.us)

**RE: AHERA 3-Year Reinspection  
Peter W. Reilly Elementary School  
115 Douglas Road  
Lowell, Massachusetts  
EFI Project No. 014.07795**

Dear Mr. Underwood:

EFI Global Inc. (EFI) is pleased to present this AHERA 3-Year Reinspection Report prepared for the Peter W. Reilly Elementary School located at 115 Douglas Road, Lowell, Massachusetts (Site). The reinspection site visit was conducted on February 20, 2024, and the corresponding report was completed in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) regulations (40 CFR 763) and Massachusetts Department of Labor Standards "Requirements for Schools Subject to AHERA" regulations (454 CMR 28.13).

EFI relied upon previous 3-Year Inspection and Management Plan Update report from 2014 prepared by Cardo ATC, and 2017 and 2020 reinspection's prepared by EFI Global Inc. The original AHERA Management Plan and other subsequent records were not made available at the school for review. EFI relied upon the 2020 table of identified ACM for this reinspection. The school's Management Plan and records should be located and kept on file at the school and the administrative offices.

EFI is pleased to provide environmental consulting services to Lowell Public Schools. This report should be kept on file with the school's AHERA records. If you have any questions regarding the contents of this report, or need of additional information, please contact either of the undersigned at (800) 659-1202. Thank you for the opportunity to serve your environmental needs.

Sincerely,  
**EFI Global, Inc.**



Derrick Calvario  
Project Manager  
MA Asbestos Inspector # AI 900703



Michael McCarter  
Senior Project Manager  
MA Asbestos Management Planner #AP 035661

# **AHERA 3-YEAR REINSPECTION**

**FOR:**

**PETER W. REILLY ELEMENTARY SCHOOL  
115 DOUGLAS ROAD  
LOWELL, MASSACHUSETTS**

**PREPARED BY:**



**155 WEST STREET, SUITE 6  
WILMINGTON, MASSACHUSETTS 01887**

**EFI PROJECT NUMBER 014.07795**

**March 13, 2024**

## TABLE OF CONTENTS

<b>INTRODUCTION.....</b>	<b>1</b>
<b>AHERA 3-YEAR REINSPECTION.....</b>	<b>2</b>
A. AHERA Records Review.....	2
B. ACM Application Types.....	3
C. ACM Assessment Criteria.....	3
D. Response Actions – General Recommendations.....	5
E. AHERA Licensing & Training Documentation.....	5
F. Asbestos Bulk Sampling.....	6
G. ACM Hazard Assessment and Recommended Response Actions.....	7
H. Cost Estimate for Recommended Response Actions.....	8

### Attachments:

Attachment A – AHERA Summary Table of ACMs and Recommended Response Actions

Attachment B – Site Plan and 2024 Reinspection Bulk Sample Locations

Attachment C - 2024 Reinspection Asbestos Bulk Sample Laboratory Report

Attachment D – Licenses and Training Certificates of Asbestos Inspector and Management Planner

## **INTRODUCTION**

EFI Global, Inc. (EFI) was retained by Lowell Public Schools to perform a 3-Year AHERA Reinspection in accordance with United States Environmental Protection (USEPA) Asbestos Hazard Emergency Response Act (AHERA) asbestos regulations (40 CFR 763) and Massachusetts Department of Labor Standards “Requirements for Schools Subject to AHERA” regulations (454 CMR 28.13). These regulations, commonly known as the “Asbestos in Schools Rule,” require under 40 CFR 763.80 and 454 CMR 28.13(2)(b)(1) that local education agencies (LEAs) must conduct a reinspection at least once every three years of all friable and nonfriable known or assumed asbestos-containing materials (ACMs). The reinspection includes all previously known and assumed ACMs, as well as any additional suspect ACM not previously included, as required by 40 CFR 763.80 and 454 CMR 28.13 in each school building leased, owned, or otherwise used as a school building. A school building is defined in 454 CMR 28.02 as including each of the following:

- Any structure suitable for use as a classroom, including a school facility such as a library, school eating facility, or facility used in the preparation of food
- Any gymnasium or other facility which is specially designed for athletic or recreational activities for an academic course in physical education
- Any other facility used for the instruction or housing of students or for the administration of educational or research programs
- Any maintenance, storage, or utility facility, including any hallway, essential to the operation of any facility described as a school building above
- Any portico or covered exterior hallway or walkway
- Any exterior portion of a mechanical system used to condition interior space.

EFI conducted a 3-year AHERA reinspection at the Peter W. Reilly Elementary School, which involved determining the condition and hazard potential of previously known and assumed ACMs, and additional confirmed and assumed ACMs observed during the 2024 reinspection. The 3-year reinspection was conducted on February 20, 2024, by Derrick Calvario and Emma Cypherd, both EPA accredited, and Massachusetts Department of Labor Standards (MADLS) licensed Asbestos Inspectors, (license numbers AI-900703 and license number AI-901189, respectively). EFI relied upon the previous 3-year AHERA reinspection report conducted by EFI in 2020. The original AHERA Management Plan and subsequent records were not made available at the school for review. The recommended response actions were prepared by MADLS-licensed Asbestos Management Planner Michael McCarter (AP-035661).

A summary of known and assumed ACM within the Peter W. Reilly Elementary School is presented in the AHERA Summary Table in **Attachment A**. Site Plans showing buildings and locations referenced in this report are presented in **Attachment B**.

The Designated Person for the Lowell Public Schools is Rick Underwood, who provided EFI with AHERA documentation for review. Rick’s contact information is:

Rick Underwood  
Director of Operations & Maintenance  
Lowell Public Schools  
155 Merrimack Street, 4<sup>th</sup> Floor  
Lowell, Massachusetts 01852  
978-674-4328  
[runderwood@lowell.k12.ma.us](mailto:runderwood@lowell.k12.ma.us)

**AHERA 3-YEAR REINSPECTION****A. AHERA Records Review**

As part of this 3-year reinspection, EFI reviewed available AHERA records for the school, in accordance with the AHERA regulation and 454 CMR 28.13(5)(f). A summary of records reviewed is provided in the table below.

<b>Review of AHERA Documentation</b> <b>Peter W. Reilly Elementary School</b> <b>115 Douglas Road, Lowell, Massachusetts</b>		
<b>Document/Record</b>	<b>Present?</b>	<b>Comment</b>
Asbestos Management Plan (on hand at school and available for review)	No	No records available at the school for review. The Cardo ATC 2014 3-Year Reinspection and Updated Management Plan is posted on the schools web site.
Designated Person Training Records (for Rick Underwood)	No	No records available at the school for review. Designated Person should receive formal designated person training or review the Designated Person Self Study Guide (available at <a href="https://www.epa.gov/sites/default/files/2015-01/documents/dp_study_guide_0.pdf">https://www.epa.gov/sites/default/files/2015-01/documents/dp_study_guide_0.pdf</a> ).
Custodial Personnel 2-hour Awareness Training Records	No	No records available at the school for review.
Annual Parental Notification Records	No	No records available at the school for review. Annual notification letters should be sent and copies kept on file with the AHERA records.
Abatement/Response Action Records (includes abatement, special cleaning activities & small scale short duration (SSSD) activities and associated monitoring reports and work plans)	No	No records available at the school for review.
Designated Person True and Correct Statement	No	No records available at the school for review.
6-month Surveillance Inspection Records	No	No records available at the school for review.
Previous 3-Year Reinspection Records	No	No records available at the school for review.
Asbestos Labels present (required in routine maintenance areas)	No	No labeling observed. Labels should be placed immediately adjacent to ACM present in routine maintenance areas (i.e., boiler rooms, utility closets, etc.)

## **B. ACM Application Types**

ACMs are divided into the following application types:

Thermal system insulation (TSI): Insulation applied to mechanical, heating, and cooling systems such as pipes, boilers, flue breechings, ducts, tanks and fittings.

Surfacing Materials: Material that is spray-applied or trowel-applied to walls, ceilings or structural components (i.e., plasters, acoustical finishes and fireproofing).

Miscellaneous Materials: All other asbestos materials, including but not limited to floor tiles and mastic, ceiling tiles, vinyl cove base and mastic, gypsum board and joint compound, and asbestos-cement board, etc.

## **C. ACM Assessment Criteria**

The assessment is divided into two categories - the physical assessment and the hazard potential assessment.

### Physical Assessment

The physical assessment is divided into the following seven categories and describes the material condition at the time of the inspection:

Physical Condition #1 - Damaged or significantly damaged thermal system ACM.

Physical Condition #2 - Damaged friable surfacing ACM.

Physical Condition #3 - Significantly damaged friable surfacing ACM.

Physical Condition #4 - Damaged or significantly damaged miscellaneous ACM.

Physical Condition #5 - ACM with potential for damage.

Physical Condition #6 - ACM with potential for significant damage.

Physical Condition #7 - Any remaining friable ACM or friable suspected ACM.

### Hazard Assessment

The hazard assessment is a combination of the physical assessment combined with the potential for disturbance (i.e., physical contact, vibration air movement) as follows:

Hazard Rank #1 – Good condition/Low potential for disturbance

Hazard Rank #2 – Good condition/ Moderate potential for disturbance

Hazard Rank #3 – Good condition/ High potential for disturbance

Hazard Rank #4 – Damaged condition/Low potential for disturbance

Hazard Rank #5 – Damaged condition/Moderate potential for disturbance

Hazard Rank #6 – Damaged condition/High potential for disturbance

Hazard Rank #7 – Significantly damaged condition

The following is the Assessment Criteria used during the inspection:

1. Homogeneous Areas (An area of surfacing material, thermal system insulation material, or miscellaneous material that is uniform in size, color and texture and was applied at approximately the same time) were quantified by location and assessed by condition. Materials are listed as friable or non-friable. Note: friable materials are materials that can be crushed and pulverized to dust by hand pressure. A general condition description for suspect materials used in this inspection is as follows:
  - a. Damaged Surfacing ACM: That material which has deterioration, delamination, water damage, lacks cohesion, is blistered, crumbling, gouged, marred heavily, abraded, or in any way has lost its structural integrity over more than 1% but less than 10 % of the total surface area if the damage is evenly distributed or less than 25%, if the damage is localized in one area of the homogeneous area.
  - b. Significantly Damaged ACM: That material which has deterioration, delamination, water damage, lacks cohesion, is blistered, crumbling, gouged, marred heavily, abraded, or in any way has lost its structural integrity over at least 10% of the surface area if the damage is evenly distributed or at least 25% if the damaged is localized.
  - c. Good Condition ACM: ACM with no visible damage or deterioration in less than one percent of the material and/or coverings.
  - d. ACM with potential for damage: Pertains to circumstances in which:
    - i. Friable ACM is in an area regularly used by building occupants, including maintenance workers, currently in intact (good) condition.
    - ii. There are indications that there is a reasonable likelihood that the material or its covering will become damaged, deteriorated or delaminated due to factors such as changes in building use, changes in O&M practices, changes in occupancy or recurrent damage.

Note: All ACM in good condition is still considered to have a potential for damage, and in certain instances, has the potential for significant damage.

- e. ACM with potential for significant damage: Pertains to circumstances in which:
  - i. Friable ACM is in an area regularly used by building occupants, including maintenance personnel.
  - ii. Indications show that there is a reasonable likelihood that the material or its covering will become damaged, deteriorated, or delaminated due to factors such as changes in building use, changes in O&M practices, changes in occupancy or re-occurring damage.
  - iii. The material is subject to major or continuing disturbance, due to factors including, but not limited to, accessibility or under certain circumstances, vibration or air erosion.

**D. Response Actions – General Recommendations**

Specific response actions for each known and assumed ACM located at the Peter W. Reilly Elementary School are located in **Attachment A**. The following are general recommendations for response actions associated with managing ACMs at the school.

1. Damaged materials in the school should be repaired, if feasible, or removed in order to maintain compliance with the AHERA regulations. Damaged ACMs of any quantity listed in the report should be repaired or removed by a Massachusetts licensed Asbestos Contractor following all applicable regulations, in accordance with a work plan design, and final clearance air testing performed in accordance with the AHERA regulations. It is the policy of the Lowell Public Schools to use licensed Asbestos Contractors for all response action work.
2. The AHERA regulation states that the response actions chosen for other than small scale/short duration repairs (less than 3 square or linear feet), must be designed and conducted by persons accredited to design and conduct response actions. MADLS Regulation 454 CMR 28.00 requires the services of licensed Project Designers who meet the requirements set forth in 454 CMR 28.00, as well as Massachusetts licensed Asbestos Contractors.
3. Damaged ACMs that involve small scale/short duration repairs can only be conducted by 16-hour asbestos-trained personnel or by a licensed Asbestos Contractor. EFI understands that small scale/ short duration projects will not be performed by in house personnel, and that all work will be conducted by an outside licensed Asbestos Contractor.
4. Each known and assumed ACM should be monitored for any changes in condition during the six-month periodic surveillance, or more frequently.
5. If known or suspect ACMs are to be impacted by planned renovation or demolition activities, the ACM must be removed by a Massachusetts licensed Asbestos Contractor. Note that AHERA inspections do not meet the EPA NESHAP and Commonwealth of Massachusetts Department of Environmental Protection (MADEP) requirements for a comprehensive pre-renovation or demolition survey. Prior to any planned renovation or demolition project, all renovation/demolition areas must be thoroughly surveyed to meet the requirements of EPA NESHAP and MADEP 310 CMR 7.15(4) Survey Requirements. LEA Designated Persons should make sure that pre-renovation/demolition surveys are performed in each instance that ACM may be disturbed.

**E. AHERA Licensing & Training Documentation**

The AHERA 3-year Reinspection report for the Peter Reilly W. School was performed by the following individuals who have received appropriate training and who are MADLS licensed personnel:



Derrick Calvario  
Project Manager  
MA Asbestos Inspector # AI 900703



Michael McCarter  
Senior Project Manager  
MA Asbestos Management Planner #AP 035661



## F. Asbestos Bulk Sampling

Asbestos bulk sampling of suspect ACM was performed for various suspect ACMs not previously identified as ACM in portions of the building included in the AHERA program. The bulk sampling by USEPA-accredited and MADLS-licensed Asbestos Inspectors Derrick Calvario and Emma Cypherd. A total of 103 bulk samples of suspect ACMs were collected and transported under chain of custody protocol to EMSL Analytical, Inc., of Woburn, Massachusetts, a Massachusetts-licensed laboratory. EMSL is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for bulk asbestos fiber analysis, which is administered by the National Institute of Standards and Testing (NIST).

Samples were analyzed with a standard 3-day turnaround time using polarized light microscopy (PLM) in accordance with United States Environmental Protection Agency (USEPA) Method 600/R-93/116. The PLM/DS analytical method is modeled after 40 CFR Part 763, Subpart F, Attachment A: "Interim Method for the Determination of Asbestos in Bulk Insulation Samples." MADEP asbestos regulations define an ACM as any material containing greater than or equal to one percent asbestos. The findings of this report are based upon observations of accessible materials and the analysis of representative bulk samples collected. **Attachment B** contains site plans indicating locations of samples collected and analyzed as part of this reinspection. A copy of the asbestos laboratory reports is presented in **Attachment C**.

Bulk samples representing individual homogenous areas of suspect ACM, (materials that are determined to be uniform in color and texture and installed in the same construction period) were collected in a randomly distributed manner, in accordance with the EPA sampling protocol outlined in 40 CFR 763.

The following suspect ACMs sampled by EFI during the 2024 reinspection were reported by EMSL as containing no detectable concentration of asbestos:

### Summary of Non-ACMs per 2024 3-Year Reinspection

Material Description	Location(s) Sampled
Ceiling Texture	Main Lobby/ Entrance
Yellow Carpet Mastic	Office Off Main Lobby, Storage Off Room Next to Literature Room
1' x 1' Brown Floor Tile Under Carpet	Office Off Main Lobby
Yellow Mastic associated with 1' x 1' Brown Floor Tile Under Carpet	Office Off Main Lobby
2" x 4" Ceiling Tile Pinhole	Hallway Side D, Music Room
Plaster Skim Coat	Kitchen Rear Right Storage Room, Room 407, Hallway Side A, Room 104, Hallway Side D
Plaster Base Coat	Kitchen Rear Right Storage Room, Room 407, Hallway Side A, Room 104, Hallway Side D
Gypsum Board	Room Next to Literature Room, Library
Joint Compound	Room Next to Literature Room, Library
2" x 4" Ceiling Tile Crows Feet	Hallway Side D/C Intersection, Room 407
1' x 1' Gray Floor Tile with White Speckle	Library

Material Description	Location(s) Sampled
Yellow Mastic associated with 1' x 1' Gray Floor Tile with White Speckle	Library
Brown Floor Leveler	Library
Cove Base	Library, K1
Tan Mastic associated with Cove Base	Library, K1
2' x 2' Ceiling Tile Pinhole	Library, Hallway Side A
2' x 2' Ceiling Tile Crows Feet	Room 104, Literature Room
Brown Felt/Roofing	Library
1' x 1' Light Blue Floor Tile with White and Blue Streak	Literature Room
Yellow Mastic associated with 1' x 1' Light Blue Floor Tile with White and Blue Streak	Literature Room
White Floor Leveler	Storage Room Off Literature Room
Cork Board	Hallway Side C
Black Mastic associated with Cork Board	Hallway Side C
6" x 6" Brown Ceramic Floor Tile Grout	Room 019
Black Mastic	Room 405, Room 402
White Ceramic Floor Tile Grout	Staff Bath
Black Mastic associated with 1' x 1' Black Floor Tile Under Red 1' x 1' Floor Tile	Room 403
1' x 1' White Floor Tile with color	Room 306
1' x 1' White Floor Tile with Tan Speckle	Room 302
Cove Base Brittle	Hallway Side A, Pre-k-3
Black Mastic associated with Cove Base Brittle	Hallway Side A, Pre-k-3
1' x 1' Ceiling Squares Pinhole	Room Ck-4 CS1-2, K1
Felt Backing above Wood Ceiling	Hallway Side B
1' x 1' Light Blue Floor Tile with Speckle	Room 101, K2
1' x 1' White Floor Tile with Streak	Main Offices
Blue Epoxy Sheet Flooring	RN Office
1' x 1' Tan Floor Tile	Room 205
Residual Black Mastic associated with 1' x 1' Tan Floor Tile	Room 205
Gray Door Caulking	Exterior Door 1
Brown Door Caulking	Exterior Door 2
Brown Window Caulking	Exterior North windows, Exterior West Windows

#### G. ACM Hazard Assessment & Recommended Response Actions

Accessible locations were inspected and assessed to determine the presence and condition of known and assumed ACM. A Summary Table of known and assumed ACMs present at the school, the physical and hazard assessments and the recommended response action for each ACM, is presented in **Attachment A**. It should be noted that EFI did not conduct destructive evaluations of the school building to identify suspect ACM. Per USEPA NESHAP and MADEP asbestos regulations, a thorough "path of construction"

survey should be conducted prior to any renovation or repair activities that may impact suspect ACM, regardless of the date of installation.

#### H. Cost Estimate and Schedule for Recommended Response Actions

The confirmed and assumed ACMs outlined in the summary table in **Attachment A** that were in good condition at the time of the reinspection must be maintained in place in accordance with the Operations and Maintenance Plan. Estimated costs associated with managing known and assumed ACMs at the school are summarized below.

<b>Cost Estimate of AHERA Considerations</b> <b>Peter W. Reilly Elementary School</b> <b>115 Douglas Road, Lowell, Massachusetts</b>	
<b>Training Costs</b>	
<b>Item</b>	<b>Approximate Cost</b>
2-hour asbestos awareness training (New Hires, within 60 days of hire)	\$500/person
Designated Person Training	\$250
<b>Maintenance Costs</b>	
<b>Item</b>	<b>Approximate Cost</b>
Asbestos labeling (Place/maintain labels adjacent to ACM in routine maintenance areas)	\$500
6-month surveillance inspections (Per schedule below)	\$500/event
3-year re-inspection (Per schedule below)	\$2,000
<b>Response Action Costs</b>	
<b>Item</b>	<b>Approximate Cost</b>
No Recommended Response Actions	N/A

A proposed schedule of events between this 3-Year reinspection and the 2027 3-Year reinspection is provided for your use:

<b>Schedule of AHERA-Related Actions</b> <b>Peter W. Reilly Elementary School</b> <b>115 Douglas Road, Lowell, Massachusetts</b>	
<b>Event</b>	<b>Completion Date</b>
6 Month Surveillance Inspection	August 20, 2024
Annual Parental Notification Letter	September 1, 2024
6 Month Surveillance Inspection	February 20, 2025
6 Month Surveillance Inspection	August, 2025
Annual Parental Notification Letter	September 1, 2025
6 Month Surveillance Inspection	February 20, 2026
6 Month Surveillance Inspection	August 20, 2026
Annual Parental Notification Letter	September 1, 2026
3 Year Reinspection	February 20, 2027

**ATTACHMENT A**

**AHERA SUMMARY TABLE**

AHERA 3 Year Reinspection Summary Table  
 Peter W. Reilly Elementary School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 115 Douglas Road, Lowell, MA  
 Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
1	Flex Joint	Boiler Room Mezzanine	4 Joints	NF	Positive per Management Plan records	6	Good	Manage in place in accordance with the Asbestos O&M Program. Rooms where vibration is present due to operating mechanical equipment can be inspected more frequently, such as every 3 months, by trained maintenance personnel.	
2	9" x 9" Brown Floor Tile	Custodian Office	15 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
3	Mastic associated with 9" x 9" Brown Floor Tile (added per 2024 reinspection)	Custodian Office	15 SF	NF	Not sampled. Assumed AC	N/A	N/A, material not accessible for inspection	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
4	Pipe thread sealant (added per 2024 reinspection)	Boiler Room	200 SF	NF	Not sampled. Assumed ACM	5	Good	Material was observed to be exposed in the boiler room. Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
5	Grey duct seam sealant (added per 2024 reinspection)	Boiler Room	100 SF	NF	Not sampled. Assumed ACM	5	Good	Material was observed to be exposed in the boiler room. Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
6	Flex Joint	Roof Room (above Gym Storage)	4 Joints	NF	Positive per Management Plan records	6	Good	Manage in place in accordance with the Asbestos O&M Program. Rooms where vibration is present due to operating mechanical equipment can be inspected more frequently, such as every 3 months, by trained maintenance personnel.	
7	"Transite" Wall Panels	Roof Room (above Gym Storage)	750 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Do not store ladders, equipment, or other objects near "transite" wall panels.	
8	Vinyl countertop (added per 2024 reinspection)	Room K01	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
9	Black sink undercoat (added per 2024 reinspection)	Room K02	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
10	Vinyl countertop (added per 2024 reinspection)	Room k02	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
11	Black sink undercoat (added per 2024 reinspection)	Room K03	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
12	Vinyl countertop (added per 2024 reinspection)	Room K03	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	

AHERA 3 Year Reinspection Summary Table  
 Peter W. Reilly Elementary School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 115 Douglas Road, Lowell, MA  
 Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
13	1' x 1' Red Floor Tile	Room K04	950 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
14	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room K04	950 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible for viewing	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
15	Black sink undercoat (added per 2024 reinspection)	Room K04	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
16	Vinyl countertop (added per 2024 reinspection)	Room K04	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
17	1' x 1' Red Floor Tile	Room K05	950 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
18	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room K05	950 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible for viewing	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
19	Black sink undercoat (added per 2024 reinspection)	Ck4 CSA-2	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
20	Black sink undercoat (added per 2024 reinspection)	Pre-K03	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
21	Black sink undercoat (added per 2024 reinspection)	Room 101	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
22	Vinyl countertop (added per 2024 reinspection)	Room 101	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	

AHERA 3 Year Reinspection Summary Table  
Peter W. Reilly Elementary School  
Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
115 Douglas Road, Lowell, MA  
Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
23	Black sink undercoat (added per 2024 reinspection)	Room 102	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
24	Vinyl countertop (added per 2024 reinspection)	Room 102	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
25	Black sink undercoat (added per 2024 reinspection)	Room 103	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
26	Black sink undercoat (added per 2024 reinspection)	Room 104	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
27	Vinyl countertop (added per 2024 reinspection)	Room 104	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
28	9" x 9" Brown Floor Tile	Room 201	550 SF	NF	Positive per Management Plan records	5	Good condition overall. ~1 square foot of cracked but intact floor tile	Good condition overall with minor cracking. Monitor to determine condition does not worsen. Manage in place in accordance with the Asbestos O&M Program or replace with new non-ACM flooring. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
29	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 201	550 SF	NF	Not sampled. Assumed ACM.	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
30	Vinyl countertop (added per 2024 reinspection)	Room 202	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
31	9" x 9" Brown Floor Tile	Room 203	525 SF	NF	Positive per Management Plan records	5	Good condition overall. ~1 square foot of cracked but intact floor tile.	Good condition overall with minor cracking. Monitor to determine condition does not worsen. Manage in place in accordance with the Asbestos O&M Program or replace with new non-ACM flooring. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	

AHERA 3 Year Reinspection Summary Table  
Peter W. Reilly Elementary School  
Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
115 Douglas Road, Lowell, MA  
Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
32	Mastic associated with 9" x 9" Brown Floor Tile (added per 2024 reinspection)	Room 203	525 SF	NF	Not sampled. Assumed ACM.	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
33	Black sink undercoat (added per 2024 reinspection)	Room 203	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
34	9" x 9" Tan/Green Floor Tile	Room 204	950 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
35	Mastic associated with 9" x 9" Tan/Green Floor Tile (added per 2024 reinspection)	Room 204	950 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
36	Black sink undercoat (added per 2024 reinspection)	Room 204	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
37	Vinyl countertop (added per 2024 reinspection)	Room 204	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
38	Vinyl countertop (added per 2024 reinspection)	Room 205	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
39	Grey sink undercoat (added per 2024 reinspection)	Room 206	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
40	Vinyl countertop (added per 2024 reinspection)	Room 206	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
41	1' x 1' Red Floor Tile	Room 207	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	



AHERA 3 Year Reinspection Summary Table  
 Peter W. Reilly Elementary School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 115 Douglas Road, Lowell, MA  
 Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
68	Mastic associated with 9" x 9" Tan/Green Floor Tile (added per 2024 reinspection)	Room 207	1,080 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
69	Black sink undercoat (added per 2024 reinspection)	Room 207	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
70	Vinyl countertop (added per 2024 reinspection)	Room 207	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
71	1' x 1' Red Floor Tile	Room 301	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
72	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 301	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
73	1' x 1' Red Floor Tile	Room 302	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
74	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 302	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
75	Grey sink undercoat (added per 2024 reinspection)	Room 302	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
76	1' x 1' Red Floor Tile	Room 303	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
77	Mastic associated with 1' x 1' Red Floor Tile	Room 303	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	

AHERA 3 Year Reinspection Summary Table  
 Peter W. Reilly Elementary School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 115 Douglas Road, Lowell, MA  
 Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
78	1' x 1' Red Floor Tile	Room 304	840 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
79	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 304	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
80	Grey sink undercoat (added per 2024 reinspection)	Room 304	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
81	1' x 1' Red Floor Tile	Room 305	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
82	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 305	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
83	Grey sink undercoat (added per 2024 reinspection)	Room 305	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
84	Grey sink undercoat (added per 2024 reinspection)	Room 306	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
85	1' x 1' Red Floor Tile	Room 307	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
86	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 307	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
87	Grey sink undercoat (added per 2024 reinspection)	Room 307	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	

AHERA 3 Year Reinspection Summary Table  
 Peter W. Reilly Elementary School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 115 Douglas Road, Lowell, MA  
 Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
88	1' x 1' Red Floor Tile	Room 401	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
89	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 401	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
90	Grey sink undercoat (added per 2024 reinspection)	Room 401	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
91	Pipe Fitting Insulation	Hall Outside Room 401	6 Elbows	NF	Positive per Management Plan records	6	Good	Manage in place in accordance with the Asbestos O&M Program. Pipe fittings that are easily accessible to students can be inspected regularly, such as every 3 months, by trained maintenance personnel.	
92	1' x 1' Red Floor Tile	Room 402	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
93	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 402	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
94	Grey sink undercoat (added per 2024 reinspection)	Room 402	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
95	1' x 1' Red Floor Tile	Room 403	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
96	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 403	1,080 SF	NF	Not Sampled. Assumed ACM	N/A	N/A, material not accessible	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	

AHERA 3 Year Reinspection Summary Table  
 Peter W. Reilly Elementary School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 115 Douglas Road, Lowell, MA  
 Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
97	1' x 1' Black floor tile below 1' x 1' Red Floor Tile (material added in 2024)	Room 403	1,080 SF	NF	5% Chrysotile Asbestos (associated mastic is non-ACM per bulk sample results from 2024)	N/A	N/A, material not accessible for inspection (except for single location sampled)	The bottom layer of floor tile is not visible for inspection. Maintain top layer of floor tile in good condition in accordance with the O&M Program.	
98	Grey sink undercoat (added per 2024 reinspection)	Room 403	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
99	1' x 1' Red Floor Tile	Room 404	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
100	Mastic associate with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 404	1,080 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible for inspection	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
101	Grey sink undercoat (added per 2024 reinspection)	Room 404	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	
102	Pipe Fitting Insulation	Hall Outside Room 404	4 Elbows	NF	Positive per Management Plan records	6	Good	Manage in place in accordance with the Asbestos O&M Program. Pipe fittings that are easily accessible to students can be inspected regularly, such as every 3 months, by trained maintenance personnel.	
103	1' x 1' Red Floor Tile	Room 405	1,080 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
104	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	Room 405	1,080 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible for inspection	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
105	Grey sink undercoat (added per 2024 reinspection)	Room 405	1 Unit	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Stored items below the sink should avoid contact with basin coating. Collect bulk samples to determine asbestos content prior to any disturbance.	

AHERA 3 Year Reinspection Summary Table  
 Peter W. Reilly Elementary School  
 Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
 115 Douglas Road, Lowell, MA  
 Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
106	Pipe Fitting Insulation	Hall Outside Room 405	3 Elbows	NF	Positive per Management Plan records	6	Good	Manage in place in accordance with the Asbestos O&M Program. Pipe fittings that are easily accessible to students and can be inspected regularly, such as every 3 months, by trained maintenance personnel.	
107	Floor Tile below Carpet	Room 407	180 SF	NF	Not Sampled, appears homogeneous to other areas of confirmed ACM. Assumed ACM.	N/A	N/A, material not accessible (except for single location inspected)	Maintain carpet in good condition. Use care when lifting carpet to not disturb floor tile. Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
108	Mastic associated with Floor Tile below Carpet (added per 2024 reinspection)	Room 407	180 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible	Maintain carpet in good condition. Use care when lifting carpet to not disturb floor tile. Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
109	Floor Tile below Carpet	Room 409	200 SF	NF	Not Sampled, appears homogeneous to other areas of confirmed ACM. Assumed ACM.	N/A	N/A, material not accessible (except in single location inspected)	Maintain carpet in good condition. Use care when lifting carpet to not disturb floor tile. Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
110	Mastic associated with Floor Tile below Carpet (added per 2024 reinspection)	Room 409	200 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible	Maintain carpet in good condition. Use care when lifting carpet to not disturb floor tile. Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
111	1' x 1' Red Floor Tile	New Office (formerly part of Main Office Lobby)	220 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile.	
112	Mastic associated with 1' x 1' Red Floor Tile (added per 2024 reinspection)	New Office (formerly part of Main Office Lobby)	220 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible for inspection	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
113	9" x 9" Brown Floor Tile	Bathroom in Principal's Office	15 SF	NF	Positive per Management Plan records	5	Good	Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity.	

AHERA 3 Year Reinspection Summary Table  
Peter W. Reilly Elementary School  
Summary Table of Identified and Assumed Asbestos-Containing Building Materials  
115 Douglas Road, Lowell, MA  
Dates of Inspection: 2/20/2024

Item	Material Description	Location	Quantity	Friability (F/NF)	Sample Results	Assessment Category	Condition	Response Actions/Notes	Recommended Completion Date
114	Mastic associated with 9" x 9" Brown Floor Tile (added per 2024 reinspection)	Bathroom in Principal's Office	15 SF	NF	Not sampled. Assumed AC	N/A	N/A, material not accessible for inspection	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
115	9" x 9" Tan/Brown Floor	Bathroom in Assistant Principal's Office	15 SF	NF	Positive per Management Plan records	5	Overall good condition, but some minor cracked but intact tile.	Good condition overall with minor cracking. Monitor to determine condition does not worsen. Manage in place in accordance with the Asbestos O&M Program or replace with new non-ACM flooring. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity.	
116	Mastic associated with 9" x 9" Tan/Brown Floor Tile	Bathroom in Assistance Principal's Office	15 SF	NF	Not sampled. Assumed AC	N/A	N/A, material not accessible for inspection	Mastic is not visible. Maintain floor tile in good condition in accordance with the O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
117	White backer board mastic (added per 2024 reinspection)	Women's room off cafeteria	200 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible for inspection	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
118	White backer board mastic (added per 2024 reinspection)	Men's room off music room	200 SF	NF	Not sampled. Assumed ACM	N/A	N/A, material not accessible for inspection	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	
119	Vinyl countertop (added per 2024 reinspection)	Art room	10 SF	NF	Not sampled. Assumed ACM	5	Good	Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance.	

SF = Square Feet

Assumed ACM = This material was not identified in the Management Plan records and was not sampled during the 2024 Re-inspection. Prior to any planned disturbance by maintenance, renovation, or demolition activities, EFI recommends bulk sampling and analysis to determine asbestos content.

For all recommended response actions, the work should be conducted by a Massachusetts licensed Asbestos Contractor and a work plan for the specific repair or removal activity should be prepared by a Massachusetts licensed Asbestos Designer.

Physical Assessment Category
1 – Damaged or Significantly Damaged Thermal System ACM
2 – Damaged Friable Surfacing ACM
3 – Significantly Damaged Surfacing ACM
4 – Damaged or Significantly Damaged Friable Miscellaneous ACM
5 – ACM with Potential for Damage
6 – ACM with Potential for Significant Damage
7 – Any Remaining friable ACM or friable suspect ACM

**ATTACHMENT B**

**SITE PLANS AND BULK SAMPLE LOCATION PLANS**





**ATTACHMENT C**

**2024 REINSPECTION ASBESTOS BULK SAMPLE REPORTS**



# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com> / [bostonlab@emsl.com](mailto:bostonlab@emsl.com)

EMSL Order: 132401076

Customer ID: EAFI66

Customer PO:

Project ID:

Attention: Derrick Calvario

EFI Global, Inc.

155 West Street

Suite 6

Wilmington, MA 01887

Phone: (978) 688-3736

Fax: (978) 688-5494

Received Date: 02/23/2024 11:50 AM

Analysis Date: 02/28/2024

Collected Date: 02/20/2024

Project: 014.07795 - Riley School; 115 Douglas Road; Lowell, MA

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
01A 132401076-0001	Main Lobby/Entrance - Ceiling Texture on Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
01B 132401076-0002	Main Lobby/Entrance - Ceiling Texture on Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
01C 132401076-0003	Main Lobby/Entrance - Ceiling Texture on Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
02A 132401076-0004	Office Off Main Lobby - Yellow Carpet Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
02B 132401076-0005	Storage Off Room next to Literature Room - Yellow Carpet Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
03A 132401076-0006	Office Off Main Lobby - 12x12 Brown Floor Tile under Carpet	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
03B 132401076-0007	Office Off Main Lobby - 12x12 Brown Floor Tile under Carpet	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
04A 132401076-0008	Office Off Main Lobby - Assoc. Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
04B 132401076-0009	Office Off Main Lobby - Assoc. Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
05A 132401076-0010	Hallway Side D - 2x4 CT Pinhole	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
05B 132401076-0011	Music Room - 2x4 CT Pinhole	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
06A 132401076-0012	Kitchen Rear Right Storage Room - Plaster Skim Coat Ceiling	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
06B 132401076-0013	Room 407 - Plaster Skim Coat Wall	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
06C 132401076-0014	Center Hallway Side A - Plaster Skim Coat Wall	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
06D 132401076-0015	Room 104 - Plaster Skim Coat Wall	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/28/2024 15:29:27



# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com/bostonlab@emsl.com>

EMSL Order: 132401076

Customer ID: EAFI66

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
06E 132401076-0016	Hallway Side A Outside Main Offices - Plaster Skim Coat Wall	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
06F 132401076-0017	Hallway Side A Outside Right Wing - Plaster Skim Coat Wall	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
06G 132401076-0018	Hallway Side D Outside Boiler Room - Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07A 132401076-0019	Kitchen Rear Right Storage Room - Plaster Base Coat Ceiling	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07B 132401076-0020	Room 407 - Plaster Base Coat Wall	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07C 132401076-0021	Center Hallway Side A - Plaster Base Coat Wall	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07D 132401076-0022	Room 104 - Plaster Base Coat Wall	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07E 132401076-0023	Hallway Side A Outside Main Offices - Plaster Base Coat Wall	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07F 132401076-0024	Hallway Side A Right Wing - Plaster Base Coat Wall	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07G 132401076-0025	Hallway D Outside Boiler Room - Plaster Base Coat	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
08A 132401076-0026	Room next to Literature Room - Gypsum Board	Brown/Gray Fibrous Homogeneous	15% Cellulose 2% Glass	83% Non-fibrous (Other)	None Detected
08B 132401076-0027	Library - Gypsum Board	Brown/Gray Fibrous Homogeneous	15% Cellulose 2% Glass	83% Non-fibrous (Other)	None Detected
09A 132401076-0028	Library Center - Joint Compound - Wall	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09B 132401076-0029	Room next to Literature Room - Joint Compound	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09C 132401076-0030	Room next to Literature Room - Joint Compound	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09D 132401076-0031	Literature Room - Joint Compound	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09E 132401076-0032	Library Center - Joint Compound	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
10A 132401076-0033	Hallway Side D/C Intersection - 2x4 CT Crows Feet	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected

Initial report from: 02/28/2024 15:29:27



# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com> / [bostonlab@emsl.com](mailto:bostonlab@emsl.com)

EMSL Order: 132401076

Customer ID: EAFI66

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
10B 132401076-0034	Room 407 - 2x4 CT Crows Feet	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
11A 132401076-0035	Library - 12x12 Gray Floor Tile w. White Spec	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
11B 132401076-0036	Library - 12x12 Gray Floor Tile w. White Spec	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
12A 132401076-0037	Library - Assoc. Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
12B 132401076-0038	Library - Assoc. Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
13A 132401076-0039	Library - Brown Floor Leveler under Tile on Concrete	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
13B 132401076-0040	Library - Brown Floor Leveler under Tile on Concrete	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
14A 132401076-0041	Library - Cove Base	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
14B 132401076-0042	K1 - Cove Base	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
15A 132401076-0043	Library - Tan Cove Base Adhesive	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
15B 132401076-0044	K1 - Tan Cove Base Adhesive	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
16A 132401076-0045	Library - 2x2 CT Pinhole	Gray/White Fibrous Homogeneous	45% Cellulose 40% Min. Wool	15% Non-fibrous (Other)	None Detected
16B 132401076-0046	Center Hallway Side A - 2x2 CT Pinhole	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
17A 132401076-0047	Literature Room - 2x2 CT Crows Feet	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
17B 132401076-0048	Room 104 - 2x2 CT Crows Feet	Gray/White Fibrous Homogeneous	50% Cellulose 35% Min. Wool	15% Non-fibrous (Other)	None Detected
18A 132401076-0049	Library - Brown Felt/Roofing above Gypsum Ceiling/Drop Ceiling	Brown Fibrous Homogeneous	98% Cellulose	2% Non-fibrous (Other)	None Detected
18B 132401076-0050	Library - Brown Felt/Roofing above Gypsum Ceiling/Drop Ceiling	Brown Fibrous Homogeneous	98% Cellulose	2% Non-fibrous (Other)	None Detected
19A 132401076-0051	Literature Room - 12x12 Light Blue Tile w. White/Blue Streak	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/28/2024 15:29:27



# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com / bostonlab@emsl.com>

EMSL Order: 132401076

Customer ID: EAFI66

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
19B 132401076-0052	Literature Room - 12x12 Light Blue Tile w. White/Blue Streak	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
20A 132401076-0053	Literature Room - Assoc. Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
20B 132401076-0054	Literature Room - Assoc. Yellow Mastic	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
21A 132401076-0055	Storage Off Room Off Literature Room - White Floor Leveler	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
21B 132401076-0056	Storage Off Room Off Literature Room - White Floor Leveler	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
22A 132401076-0057	Hallway Side C - Cork Board on Wall	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
22B 132401076-0058	Hallway Side C - Cork Board on Wall	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
23A 132401076-0059	Hallway Side C - Assoc. Black Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
23B 132401076-0060	Hallway Side C - Assoc. Black Mastic	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
24A 132401076-0061	Room 019 - 6x6 Brown Ceramic Floor Tile Grout	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
24B 132401076-0062	Room 019 - 6x6 Brown Ceramic Floor Tile Grout	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
26A 132401076-0063	Room 405 - Assoc. Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
26B 132401076-0064	Room 402 - Assoc. Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
27A 132401076-0065	Staff Bath - White Floor Ceramic Squares Grout	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
27B 132401076-0066	Staff Bath - White Floor Ceramic Squares Grout	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
28A 132401076-0067	Room 403 - 12x12 Black Floor Tile under Red Floor Tile	Brown Non-Fibrous Homogeneous		95% Non-fibrous (Other)	5% Chrysotile
28B 132401076-0068	Room 403 - 12x12 Black Floor Tile under Red Floor Tile				Positive Stop (Not Analyzed)
29A 132401076-0069	Room 403 - Assoc. Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
29B 132401076-0070	Room 403 - Assoc. Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/28/2024 15:29:27



# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com / bostonlab@emsl.com>

EMSL Order: 132401076

Customer ID: EAFI66

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
30A 132401076-0071	Room 306 - 12x12 White Floor Tile w. Color	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
30B 132401076-0072	Room 306 - 12x12 White Floor Tile w. Color	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
31A 132401076-0073	Room 302 - 12x12 White Floor Tile w. Tan Spec	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
31B 132401076-0074	Room 302 - 12x12 White Floor Tile w. Tan Spec	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
32A 132401076-0075	Pre K-3 - Cove Base Brittle	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
32B 132401076-0076	Hallway Side A - Cove Base Brittle	Black/Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
33A 132401076-0077	Pre K-3 - Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
33B 132401076-0078	Hallway Side A - Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
34A 132401076-0079	Room CK-4 CS1-2 - 1x1 Pinhole CT Squares	Brown/Tan Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
34B 132401076-0080	K1 - 1x1 Pinhole CT Squares	Brown/Tan Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
35A 132401076-0081	Hallway Side B Outside 306 - Felt Backing above Wood Ceilings	Black Fibrous Homogeneous	95% Glass	5% Non-fibrous (Other)	None Detected
35B 132401076-0082	Hallway Side B Outside 305 - Felt Backing above Wood Ceilings	Black Fibrous Homogeneous	95% Glass	5% Non-fibrous (Other)	None Detected
36A 132401076-0083	Room 101 - 12x12 Light Blue Floor Tile w. Spec	Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
36B 132401076-0084	K2 - 12x12 Light Blue Floor Tile w. Spec	Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
37A 132401076-0085	Main Offices - 12x12 White Floor Tile w. Streak	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
37B 132401076-0086	Main Offices - 12x12 White Floor Tile w. Streak	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
38A 132401076-0087	RN Office - Blue Epoxy Sheet Flooring	White/Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
38B 132401076-0088	RN Office - Blue Epoxy Sheet Flooring	White/Blue Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected



# EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com / bostonlab@emsl.com>

EMSL Order: 132401076

Customer ID: EAFI66

Customer PO:

Project ID:

## Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
39A <small>132401076-0089</small>	Exterior Door #1 - Gray Door Caulking	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
39B <small>132401076-0090</small>	Exterior Door #1 - Gray Door Caulking	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
40A <small>132401076-0091</small>	Exterior Door #2 - Brown Door Caulking	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
40B <small>132401076-0092</small>	Exterior Door #2 - Brown Door Caulking	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
41A <small>132401076-0093</small>	Room 205 - 12x12 Tan Floor Tile	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
41B <small>132401076-0094</small>	Room 205 - 12x12 Tan Floor Tile	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
42A <small>132401076-0095</small>	Room 205 - Assoc. Residual Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
42B <small>132401076-0096</small>	Room 205 - Assoc. Residual Black Mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
43A <small>132401076-0097</small>	Exterior W - Brown Caulk on Exterior Windows	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
43B <small>132401076-0098</small>	Exterior N - Brown Caulk on Exterior Windows	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Analyst(s)

John McCarthy (97)

Steve Grise, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-139, VT AL998919, ME LB-0039

Initial report from: 02/28/2024 15:29:27





132401076

BOSTON NORTH

155 West Street | Suite 6 | Wilmington, MA 01887 | PHONE 978.688.3736 | FAX 978.688.5494 | FREE 800.659.1202

## BULK SAMPLE CHAIN OF CUSTODY FORM

Report to (Inspector Name):	Derrick Calvario	Bill To:	Accounts Payable
Company:	EFI Global, Inc.	Address:	Same
Address:	155 West Street Suite 6	City, State, Zip:	Same
City, State, Zip:	Wilmington, MA 01887	Telephone:	800-659-1202
Inspector Cell:	781-825-5012	Email:	US-EFIGlobal-BostonEnviroPC@efiglobal.com
Project Information			
Project No./ Description:	014.07795 - 40 June St, Lowell, MA (Riley School)		
Email Report to:	Derrick.Calvario@efiglobal.com → 115 Douglas Rd. Lowell, MA		
Alternate:			
Requested Turnaround Time:			
<input type="checkbox"/> RUSH (6hr)	<input type="checkbox"/> 1 day (24hr)	<input type="checkbox"/> 2 day (48hr)	<input checked="" type="checkbox"/> 3 day (72hr)
<input type="checkbox"/> 5 day			
Media and Methodology			
Type of Analysis:	PLM		Check for Positive Stop: <input checked="" type="checkbox"/>
Notes:	Analyze all plaster and joint compound samples		Date Collected: 2/20/24

Sample ID	Type of Material	Location
01A	Ceiling texture on plaster	Main lobby/entrance
01B	" "	" "
01C	" "	" "
02A	Yellow Carpet mastic	office off main lobby
02B	" "	Storage off room next to Literature room
03A	12x12 Brown floor tile under carpet	office off main lobby
03B	" "	" "
04A	associated yellow mastic	" "
04B	" "	" "

Total Number of Samples Submitted: 103

Samplers Name: Derrick Calvario

Samplers Signature:

Relinquished By (Client):

REC'D

EMSL-BOSTON

Date: 2/23/24

Time: —

Received By (Lab):

Date: — Time: —





132401076

Sample ID	Type of Material	Location
05A	2x4 CT pinhole	Hallway Side D
05B	" "	MUSIC room
06A	Plaster skim Coat Ceiling	Kitchen near right storage room
06B	" " wall	Rm 407
06C	" " wall	Center Hallway Side A
06D	" " wall	Rm 104
06E	" " wall	Hallway Side A outside main offices
06F	" " wall	" " right wing
06G	" "	Hallway side D outside boiler room
07A	Plaster Base Coat Ceiling	Kitchen near right storage room
07B	" " wall	Rm 407
07C	" " wall	Center Hallway Side A
07D	" " wall	Rm 104
07E	" " wall	Hallway Side A outside main offices
07F	" " wall	" " right wing
07G	" "	Hallway Side D outside boiler room
08A	Gypsum board	room next to Literature room
08B	" "	Library
09A	Joint Compound - wall	Library Center
09B	" "	Room next to literature room
09C	" "	<del>Room</del> " "
09D	" "	Literature room
09E	" "	Library Center
<del>09F</del>	<del>" "</del>	<del></del>
<del>09G</del>	<del>" "</del>	<del></del>
10A	2x4 CT Crows feet	Hallway side D/C intersection
10B	" "	Rm 407
11A	12x12 gray tile w/ white spec	Library
11B	" "	" "
12A	associated yellow mastic	" "

REC'D

EMSL-BOSTON

FEB 23 2024





132401076

Sample ID	Type of Material	Location
12B	associated Yellow mastic	Library
13A	<sup>brown</sup> floor leveler under tile on concrete	" "
13B	" "	" "
14A	Cave base	Library
14B	" "	K1
15A	Tan Cave base adhesive	Library
15B	" "	K1
16A	2x2 CT pin hole	Library
16B	" "	Center Hallway Asee A
17A	2x2 CT Crows feet	Literature room
17B	" "	<del>Center Hallway Asee A</del> Rm 104
18A	<sup>brown</sup> felt / roofing above gypsum ceiling/drop ceiling	Library
18B	" "	" "
19A	12x12 light blue tile w/ white/blue streak	Literature room
19B	" "	" "
20A	associated Yellow mastic	" "
20B	" "	" "
21A	white floor leveler	Storage off room off literature room
21B	" "	" "
22A	Cork board on wall	Hallway Side C
22B	" "	" "
23A	associated black mastic	H1
23B	" "	" "
24A	6x6 brown Ceramic floor grout	Rm 019
24B	" "	" "
<del>25A</del>	<del>12x12 red floor tile VOID</del>	<del>Rm 405</del>
<del>25B</del>	<del>" " VOID</del>	<del>Rm 402</del>
26A	<sup>associated</sup> black mastic	Rm 405
26B	" "	Rm 402

REC'D

EMSL-BOSTON

FEB 23 2024





132401076

Sample ID	Type of Material	Location
27A	<sup>white floor</sup> Ceramic Squares grout	Staff bath
27B	" "	" "
28A	12x12 black fl tile under red tile	Rm 403
28B	" "	" "
29A	associated black mastic	" "
29B	" "	" "
30A	12x12 white fl tile w/ Color	Rm 306
30B	" "	" "
31A	12x12 white fl tile w/ tan spec	Rm 302
31B	" "	" "
32A	Cave base brittle <del>tile</del>	Prek-3
32B	" "	Hallway side A
33A	black mastic	Prek-3
33B	" "	Hallway side A
34A	1x1 Pinhole CT Squares	Rm CLKY CST-2
34B	1x1 Pinhole CT Squares	<del>Rm</del> K1
35A	felt backing above wood ceilings	Hallway side B outside 306
35B	" "	" " outside 305
36A	12x12 light blue fl tile w/spec	Rm 101
36B	" "	K2
37A	12x12 white fl tile w/streak	Main offices
37B	" "	" "
38A	blue epoxy sheet flooring	RN office
38B	" "	RN office
39A	gray door Caulking	Exterior door #1
39B	" "	" "
40A	Brown door Caulking	Exterior door #2
40B	" "	" "
41A	12x12 Tan fl tile	Rm 205
41B	" "	" "

REC'D

EMSL-BOSTON

FEB 23 2024



REC'D 5117  
EMSL-BOSTON FEB 23 2024

**ATTACHMENT D**

**LICENSES AND TRAINING CERTIFICATES OF ASBESTOS INSPECTOR & MANAGEMENT PLANNER**



THE COMMONWEALTH OF MASSACHUSETTS  
EXECUTIVE OFFICE OF LABOR AND WORKFORCE DEVELOPMENT  
DEPARTMENT OF LABOR STANDARDS

Michael Flanagan  
Director

**ASBESTOS INSPECTOR**

**DERRICK W. CALVARIO**

**Eff.Date: 11/03/2023**

**Exp.Date: 11/02/2024**

**AI900703**

**Member C.O.N.E.S.**

**WB - NEW**

24





*This is to certify that*

**Derrick W. Calvario**

39 Valleywood Road, Hopkinton, MA 01748

MA DLS Asbestos Inspector License# AI900703



*has completed requisite training by Video Conference, and has passed an examination for  
reaccreditation as:*

**Asbestos Inspector Refresher**

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location

Zoom Video Conference

Institute for Environmental Education 16 Upton Drive Wilmington, MA 01887

August 3, 2023

Course Dates

23-4811-106-265405

Certificate Number

August 03, 2023

Examination Date

August 03, 2024

Expiration Date

Training Director

16 Upton Drive, Wilmington, MA 01887

Telephone 978.658.5272

www.ieetrains.com

**INSTITUTE FOR ENVIRONMENTAL EDUCATION**





THE COMMONWEALTH OF MASSACHUSETTS  
EXECUTIVE OFFICE OF LABOR AND WORKFORCE DEVELOPMENT  
DEPARTMENT OF LABOR STANDARDS

Michael Flanagan  
Director

**ASBESTOS MANAGEMENT PLANNER**

**MICHAEL MCCARTER**

**Eff.Date: 09/08/2023**

**Exp.Date: 09/07/2024**

**AP035661**

**Member C.O.N.E.S.**



24





*This is to certify that*

**Michael L McCarter**

7 Millstone Road, Windham, NH 03087

MA DLS Asbestos Management Planner License# AP035661



*has completed the requisite training by Video Conference, and has passed an examination for  
reaccreditation*

**Asbestos Management Planner Refresher**

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location

Zoom Video Conference

Institute for Environmental Education 16 Upton Drive Wilmington, MA 01887

April 21, 2023

Course Dates

23-4930-136-219102

Certificate Number

April 21, 2023

Examination Date

April 21, 2024

Expiration Date

Training Director

16 Upton Drive, Wilmington, MA 01887

Telephone 978.658.5272

www.ieetrains.com

**INSTITUTE FOR ENVIRONMENTAL EDUCATION**