

March 22, 2024

Rick Underwood
Director of Operations & Maintenance
Lowell Public Schools
155 Merrimack Street, 4th Floor
Lowell, Massachusetts 01852

via email: runderwood@lowell.k12.ma.us

**RE: AHERA 3-Year Reinspection
Riverside School
73 Woburn Street
Lowell, Massachusetts
EFI Project No. 014.07795**

Dear Mr. Underwood:

EFI Global Inc. (EFI) is pleased to present this AHERA 3-Year Reinspection Report prepared for the Riverside School located at 73 Woburn Street, Lowell, Massachusetts (Site). The reinspection site visit was conducted on February 22, 2024, and the corresponding report was completed in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) regulations (40 CFR 763) and Massachusetts Department of Labor Standards "Requirements for Schools Subject to AHERA" regulations (454 CMR 28.13).

EFI relied upon previous 3-Year Inspection and Management Plan Update report from 2014 prepared by Cardo ATC, and 2017 and 2020 reinspection's prepared by EFI Global Inc. The original AHERA Management Plan and other subsequent records were not made available at the school for review. EFI relied upon the 2020 table of identified ACM along with visual assessment and bulk sampling of new materials for this reinspection. The school's Management Plan and records should be located and kept on file at the school and the administrative offices.

EFI is pleased to provide environmental consulting services to Lowell Public Schools. This report should be kept on file with the school's AHERA records. If you have any questions regarding the contents of this report, or are in need of additional information, please contact either of the undersigned at (800) 659-1202. Thank you for the opportunity to serve your environmental needs.

Sincerely,
EFI Global, Inc.



Derrick Calvario
Project Manager
MA Asbestos Inspector # AI 900703



Michael McCarter
Senior Project Manager
MA Asbestos Inspector # AI 001825
MA Asbestos Management Planner #AP 035661

AHERA 3-YEAR REINSPECTION

FOR:

**RIVERSIDE SCHOOL
73 WOBURN STREET
LOWELL, MASSACHUSETTS**

PREPARED BY:



**155 WEST STREET, SUITE 6
WILMINGTON, MASSACHUSETTS 01887**

EFI PROJECT NUMBER 014.07795

March 22, 2024

TABLE OF CONTENTS

| | |
|----------------------------------------------------------------|----------|
| INTRODUCTION..... | 1 |
| AHERA 3-YEAR REINSPECTION..... | 2 |
| A. AHERA Records Review..... | 2 |
| B. ACM Application Types..... | 3 |
| C. ACM Assessment Criteria..... | 3 |
| D. Response Actions – General Recommendations..... | 5 |
| E. AHERA Licensing & Training Documentation..... | 5 |
| F. Asbestos Bulk Sampling..... | 6 |
| G. ACM Hazard Assessment and Recommended Response Actions..... | 7 |
| H. Cost Estimate for Recommended Response Actions..... | 7 |

Attachments:

Attachment A – AHERA Summary Table of ACMs and Recommended Response Actions

Attachment B – Site Plans and 2024 Reinspection Bulk Sample Locations

Attachment C - 2024 Reinspection Asbestos Bulk Sample Laboratory Report

Attachment D – Licenses and Training Certificates of Asbestos Inspector and Management Planner

INTRODUCTION

EFI Global, Inc. (EFI) was retained by Lowell Public Schools to perform a 3-Year AHERA Re-inspection in accordance with United States Environmental Protection (USEPA) Asbestos Hazard Emergency Response Act (AHERA) asbestos regulations (40 CFR 763) and Massachusetts Department of Labor Standards “Requirements for Schools Subject to AHERA” regulations (454 CMR 28.13). These regulations, commonly known as the “Asbestos in Schools Rule,” require under 40 CFR 763.80 and 454 CMR 28.13(2)(b)(1) that local education agencies (LEAs) must conduct a reinspection at least once every three years of all friable and nonfriable known or assumed asbestos-containing materials (ACMs) and any not previously identified suspect ACM, regardless of whether or not these areas were included in the original inspection and management plan, in each school building that they lease, own, or otherwise use as a school building. A school building is defined in 454 CMR 28.02 as including each of the following:

- Any structure suitable for use as a classroom, including a school facility such as a library, school eating facility, or facility used in the preparation of food
- Any gymnasium or other facility which is specially designed for athletic or recreational activities for an academic course in physical education
- Any other facility used for the instruction or housing of students or for the administration of educational or research programs
- Any maintenance, storage, or utility facility, including any hallway, essential to the operation of any facility described as a school building above
- Any portico or covered exterior hallway or walkway
- Any exterior portion of a mechanical system used to condition interior space.

EFI conducted a 3-year AHERA re-inspection at the Riverside School, which involved determining the condition and hazard potential of previously identified ACMs and newly identified ACMs. The 3-year re-inspection was conducted on February 22, 2024, by Derrick Calvario an EPA accredited, and Massachusetts Department of Labor Standards (MADLS) licensed Asbestos Inspector, (license number AI-900703). EFI relied upon the 2020 table of identified ACM along with visual assessment and bulk sampling of new materials for this reinspection. The original AHERA Management Plan and subsequent records were not made available at the school for review. The recommended response actions were prepared by MADLS-licensed Asbestos Management Planner Michael McCarter (AP-035661).

A summary of known and assumed ACM within the Riverside School is presented in the AHERA Summary Table in **Attachment A**. Site Plans showing buildings and locations referenced in this report are presented in **Attachment B**.

The Designated Person for the Lowell Public Schools is Rick Underwood. Rick’s contact information is:

Rick Underwood
Director of Operations & Maintenance
Lowell Public Schools
155 Merrimack Street, 4th Floor
Lowell, Massachusetts 01852
978-674-4328
runderwood@lowell.k12.ma.us

AHERA 3-YEAR REINSPECTION**A. AHERA Records Review**

As part of this 3-year reinspection, EFI reviewed available AHERA records for the school, in accordance with the AHERA regulation and 454 CMR 28.13(5)(f). A summary of records reviewed is provided in the table below.

| Review of AHERA Documentation Riverside School 73 Woburn Street, Lowell, Massachusetts | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Document/Record | Present? | Comment |
| Asbestos Management Plan (on hand at school and available for review) | No | No records available at the school or administrative offices for review. The Cardo ATC 2014 3-Year Reinspection and Updated Management Plan is posted on the school web site. EFI also relied upon in-house records from the 2017 and 2020 reinspections. |
| Designated Person (Rick Underwood) Training Records | No | No records available at the school or administrative offices for review. Designated Person should receive formal designated person training or review the Designated Person Self Study Guide (available at https://www.epa.gov/sites/default/files/2015-01/documents/dp_study_guide_0.pdf). |
| Custodial Personnel 2-hour Awareness Training Records | No | No records available at the school or administrative offices for review. |
| Annual Parental Notification Records | No | No records available at the school or administrative offices for review. Annual notification letters should be sent, and copies kept on file with the AHERA records. |
| Abatement/Response Action Records (includes abatement, special cleaning activities & small-scale short duration (SSSD) activities and associated monitoring reports and work plans) | No | No records available at the school or administrative offices for review. |
| Designated Person True and Correct Statement | No | No records available at the school or administrative offices for review. |
| 6-month Surveillance Inspection Records | No | No records available at the school or administrative offices for review. |
| Previous 3-Year Reinspection Records | Yes | No records available at the school or administrative offices for review. |
| Asbestos Labels present (required in routine maintenance areas) | No | No labels observed. Labels should be placed immediately adjacent to ACM present in routine maintenance areas (i.e., boiler rooms, utility closets, etc.) |

B. ACM Application Types

ACMs are divided into the following application types:

Thermal system insulation (TSI): Insulation applied to mechanical, heating, and cooling systems such as pipes, boilers, flue breechings, ducts, tanks and fittings.

Surfacing Materials: Material that is spray-applied or trowel-applied to walls, ceilings or structural components (i.e. plasters, acoustical finishes and fireproofing).

Miscellaneous Materials: All other asbestos materials, including but not limited to floor tiles and mastic, ceiling tiles, vinyl cove base and mastic, gypsum board and joint compound, and asbestos-cement board, etc.

C. ACM Assessment Criteria

The assessment is divided into two categories - the physical assessment and the hazard potential assessment.

Physical Assessment

The physical assessment is divided into the following seven categories and describes the material condition at the time of the inspection:

Physical Condition #1 - Damaged or significantly damaged thermal system ACM.

Physical Condition #2 - Damaged friable surfacing ACM.

Physical Condition #3 - Significantly damaged friable surfacing ACM.

Physical Condition #4 - Damaged or significantly damaged miscellaneous ACM.

Physical Condition #5 - ACM with potential for damage.

Physical Condition #6 - ACM with potential for significant damage.

Physical Condition #7 - Any remaining friable ACM or friable suspected ACM.

Hazard Assessment

The hazard assessment is a combination of the physical assessment combined with the potential for disturbance (i.e., physical contact, vibration air movement) as follows:

Hazard Rank #1 – Good condition/Low potential for disturbance

Hazard Rank #2 – Good condition/ Moderate potential for disturbance

Hazard Rank #3 – Good condition/ High potential for disturbance

Hazard Rank #4 – Damaged condition/Low potential for disturbance

Hazard Rank #5 – Damaged condition/Moderate potential for disturbance

Hazard Rank #6 – Damaged condition/High potential for disturbance

Hazard Rank #7 – Significantly damaged condition

The following is the Assessment Criteria used during the inspection:

1. Homogeneous Areas (An area of surfacing material, thermal system insulation material, or miscellaneous material that is uniform in size, color and texture and was applied at approximately the same time) were quantified by location and assessed by condition. Materials are listed as friable or non-friable. Note: friable materials are materials that can be crushed and pulverized to dust by hand pressure. A general condition description for suspect materials used in this inspection is as follows:
 - a. Damaged Surfacing ACM: That material which has deterioration, delamination, water damage, lacks cohesion, is blistered, crumbling, gouged, marred heavily, abraded, or in any way has lost its structural integrity over more than 1% but less than 10 % of the total surface area if the damage is evenly distributed or less than 25%, if the damage is localized in one area of the homogeneous area.
 - b. Significantly Damaged ACM: That material which has deterioration, delamination, water damage, lacks cohesion, is blistered, crumbling, gouged, marred heavily, abraded, or in any way has lost its structural integrity over at least 10% of the surface area if the damage is evenly distributed or at least 25% if the damaged is localized.
 - c. Good Condition ACM: ACM with no visible damage or deterioration in less than one percent of the material and/or coverings.
 - d. ACM with potential for damage: Pertains to circumstances in which:
 - i. Friable ACM is in an area regularly used by building occupants, including maintenance workers, currently in intact (good) condition.
 - ii. There are indications that there is a reasonable likelihood that the material or its covering will become damaged, deteriorated or delaminated due to factors such as changes in building use, changes in O&M practices, changes in occupancy or recurrent damage.

Note: All ACM in good condition is still considered to have a potential for damage, and in certain instances, has the potential for significant damage.

- e. ACM with potential for significant damage: Pertains to circumstances in which:
 - i. Friable ACM is in an area regularly used by building occupants, including maintenance personnel.
 - ii. Indications show that there is a reasonable likelihood that the material or its covering will become damaged, deteriorated, or delaminated due to factors such as changes in building use, changes in O&M practices, changes in occupancy or re-occurring damage.
 - iii. The material is subject to major or continuing disturbance, due to factors including, but not limited to, accessibility or under certain circumstances, vibration or air erosion.

D. Response Actions – General Recommendations

Specific response actions for each known and assumed ACM located at the Riverside School are located in **Attachment A**. The following are general recommendations for response actions associated with managing ACMs at the school.

1. Damaged materials in the school should be repaired, if feasible, or removed in order to maintain compliance with the AHERA regulations. Damaged ACMs of any quantity listed in the report should be repaired or removed by a Massachusetts licensed asbestos abatement contractor following all applicable regulations, in accordance with a work plan design, and final clearance air testing performed in accordance with the AHERA regulations. It is the policy of the Lowell Public Schools to use licensed asbestos contractors for all response action work.
2. AHERA regulations state that the response actions chosen for other than small scale/short duration repairs (less than 3 square or linear feet), must be designed and conducted by persons accredited to design and conduct response actions. MADLS Regulation 454 CMR 28.00 requires the services of licensed Project Designers who meet the requirements set forth in 454 CMR 28.00, as well as Massachusetts licensed Asbestos Contractors.
3. Damaged ACMs that involve small scale/short duration repairs can only be conducted by 16-hour asbestos-trained personnel or by a licensed asbestos abatement contractor. EFI understands that small scale/ short duration projects will not be performed by in house personnel, and that all work will be conducted by an outside licensed Asbestos Contractor.
4. Each known and assumed ACM should be monitored for any changes in condition during the six-month periodic surveillance.
5. If known or suspect ACMs are to be impacted by planned renovation or demolition activities, the ACM must be removed by a Massachusetts licensed Asbestos Contractor. Note that AHERA inspections do not meet the EPA NESHAP and Commonwealth of Massachusetts Department of Environmental Protection (MADEP) requirements for a comprehensive pre-renovation or demolition survey. Prior to any planned renovation or demolition project, all renovation/demolition areas must be thoroughly surveyed to meet the requirements of EPA NESHAP and MADEP 310 CMR 7.15(4) Survey Requirements. LEA Designated Persons should make sure that pre-renovation/demolition surveys are performed in each instance that ACM may be disturbed.

E. AHERA Licensing & Training Documentation

The AHERA 3-year Reinspection report for the Riverside School was performed by the following individuals who have received appropriate training and who are MADLS licensed personnel:



Derrick Calvario
Project Manager
MA Asbestos Inspector # AI 900703



Michael McCarter
Senior Project Manager
MA Asbestos Management Planner #AP 035661

F. Asbestos Bulk Sampling

Asbestos bulk sampling of suspect ACM was performed for various suspect ACMs not previously identified as ACM in portions of the building included in the AHERA program. The bulk sampling was performed by USEPA-accredited, and MADLS licensed Asbestos Inspector Derrick Calvario. A total of 43 bulk samples of suspect ACMs were collected and transported under chain of custody protocol to EMSL Analytical, Inc., of Woburn, Massachusetts, a Massachusetts-licensed laboratory. EMSL is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for bulk asbestos fiber analysis, which is administered by the National Institute of Standards and Testing (NIST).

Samples were analyzed with a standard 3-day turnaround time using polarized light microscopy (PLM) in accordance with United States Environmental Protection Agency (USEPA) Method 600/R-93/116. The PLM/DS analytical method is modeled after 40 CFR Part 763, Subpart F, Attachment A: "Interim Method for the Determination of Asbestos in Bulk Insulation Samples." MADEP asbestos regulations define an ACM as any material containing greater than or equal to one percent asbestos. The findings of this report are based upon observations of accessible materials and the analysis of representative bulk samples collected. **Attachment B** contains site plans indicating locations of samples collected and analyzed as part of this reinspection. A copy of the asbestos laboratory reports is presented in **Attachment C**.

Bulk samples representing individual homogenous areas of suspect ACM, (materials that are determined to be uniform in color and texture and installed in the same construction period) were collected in a randomly distributed manner, in accordance with the EPA sampling protocol outlined in 40 CFR 763.

The following suspect ACMs sampled by EFI during the 2024 reinspection were reported by EMSL as containing no detectable concentration of asbestos:

Summary of Non-ACMs per 2024 3-Year Reinspection

| Material Description | Location(s) |
|------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Plaster Skim Coat | Social Studies/ Science Room, ELA Room, Community Room 1 st Floor, 1 st Floor Hallways, 2 nd Floor Hallways, 2 nd Floor Hallways |
| Plaster Base Coat | Social Studies/ Science Room, ELA Room, Community Room 1 st Floor, 1 st Floor Hallways, 2 nd Floor Hallways, 2 nd Floor Hallways |
| 1' x 1' Tan Floor Tile with Fleck | Office/ Special Programming 1 st Floor |
| Yellow Mastic associated with all 1' x 1' Floor Tile | Office/ Special Programming 1 st Floor |
| Black Mastic associated with 1' x 1' Floor Tile Under all 1' x 1' Floor Tile | Office/ Special Programming 1 st Floor |
| 1' x 1' Tan Floor Tile with Fleck | Bathroom 1 st Floor |
| 2' x 4' Ceiling Tile Pinhole | Bathroom 1 st Floor, 2 nd Floor Recreational Room |
| 2' x 4' Ceiling Tile Large Fissure | Bathroom 1 st Floor, 2 nd Floor Recreational Room |
| Cove Base | 1 st Floor off ELA Room |

| Material Description | Location(s) |
|-----------------------------------------|---------------------------------------------------------------------------------------------------------------|
| Yellow Mastic associated with Cove Base | 1 st Floor off ELA Room |
| Gypsum Board | 1 st Floor Staircase, 1 st Floor Bathroom off Hallway |
| Joint Compound | 1 st Floor Hallway, 1 st Floor Bathroom off Hallway, 2 nd Floor rear Hallway |
| White Caulking | Exterior Windows |

G. ACM Hazard Assessment & Recommended Response Actions

Accessible locations were inspected and assessed to determine the presence and condition of ACM. A Summary Table of known and assumed ACMs present at the school, the physical and hazard assessments and the recommended response action for each ACM, is presented in **Attachment A**. It should be noted that EFI did not conduct destructive evaluations of the school building to identify suspect ACM. Per USEPA NESHAP and MADEP asbestos regulations, a thorough “path of construction” survey should be conducted prior to any renovation or repair activities that may impact suspect ACM, regardless of the date of installation.

H. Cost Estimate and Schedule for Recommended Response Actions

The confirmed and assumed ACMs outlined in the summary table in **Attachment A** that were in good condition at the time of the assessment must be maintained in place in accordance with the Operations and Maintenance Plan. Estimated costs associated with managing ACMs at the school are summarized below.

| Cost Estimate of AHERA Considerations Riverside School 73 Woburn Street, Lowell, Massachusetts | |
|---------------------------------------------------------------------------------------------------------------|-------------------------|
| Training Costs | |
| Item | Approximate Cost |
| 2-hour asbestos awareness training (New Hires, within 60 days of hire) | \$500/person |
| Designated Person Training | \$250 |
| Maintenance Costs | |
| Item | Approximate Cost |
| Asbestos labeling (Place/maintain labels adjacent to ACM in routine maintenance areas) | \$500 |
| 6-month surveillance inspections (Per schedule below) | \$500/event |
| 3-year re-inspection (Per schedule below) | \$2,000 |
| Response Action Costs | |
| Item | Approximate Cost |
| No Recommended response actions | |

A proposed schedule of events between this 3-Year reinspection and the 2027 3-Year reinspection is provided for your use:

| Schedule of AHERA-Related Actions Riverside School 73 Woburn Street, Lowell, Massachusetts | |
|-----------------------------------------------------------------------------------------------------------|------------------------|
| Event | Completion Date |
| 6 Month Surveillance Inspection | August 22, 2024 |
| Annual Parental Notification Letter | September 1, 2024 |
| 6 Month Surveillance Inspection | February 22, 2025 |
| 6 Month Surveillance Inspection | August 22, 2025 |
| Annual Parental Notification Letter | September 1, 2025 |
| 6 Month Surveillance Inspection | February 22, 2026 |
| 6 Month Surveillance Inspection | August 22, 2026 |
| Annual Parental Notification Letter | September 1, 2026 |
| 3 Year Reinspection | February 22, 2027 |

ATTACHMENT A

AHERA SUMMARY TABLE

AHERA 3 Year Re-Inspection Summary Table
Riverside School
Summary Table of Identified and Assumed Asbestos-Containing Building Materials
73 Woburn Street, Lowell, MA
Dates of Inspection: 2/22/2024

| Item | Material Description | Location | Quantity | Friability (F/NF) | Sample Results | Assessment Category | Condition | Response Actions/ Notes | Recommended Completion Date |
|------|----------------------------------------------------------------------|-------------------------------------------------------|----------------------------|-------------------|------------------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|
| 1 | Pipe Elbow Insulation | Basement – Storage Behind Gated Area Under Rear Stair | 2 Elbows | NF | Positive per Management Plan records | 6 | Good | Manage in place in accordance with the Asbestos O&M Program. Avoid storing items near the pipe fitting insulation. Routine inspections of ACM for physical damages due to contact or other factors can be performed more frequently such as every three months. | |
| 2 | Pipe Insulation | Basement – Storage Behind Gated Area Under Rear Stair | 5 LF | NF | Positive per Management Plan records | 5 | Good | Manage in place in accordance with the Asbestos O&M Program. Avoid storing items near the pipe fitting insulation. Routine inspections of ACM for physical damages due to contact or other factors can be performed more frequently such as every three months. | |
| 3 | Fire Brick | Basement – Boiler Room | 960 SF – Not observed 2024 | NF | Assumed Positive per Management Plan records | 5 | NA | Not observed. Possibly inside boiler. Manage in place in accordance with the Asbestos O&M Program. Collect bulk samples to determine asbestos content prior to any disturbance. | |
| 4 | 1’ x 1’ White w/ Fleck Floor Tile (material added in 2024) | Spiegel’s Office/ Special Programming | 300 SF | NF | 5% Chrysotile asbestos, (associated mastic is non-ACM per bulk sample results from 2024) | 6 | Good condition overall with minor cracking. Tile is intact. | Good condition overall with minor cracking. Monitor to determine condition does not worsen. Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile. | |
| 5 | 1’ x 1’ Brown w/ Fleck Floor Tile (material added in 2024) | Spiegel’s Office/ Special Programming | 100 SF | NF | 5% Chrysotile asbestos, (associated mastic is non-ACM per bulk sample results from 2024) | 6 | Good | Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile. | |
| 6 | 1’ x 1’ Floor Tile under 1’ x 1’ Floor Tile (material added in 2024) | Spiegel’s Office/ Special Programming | 400 SF | NF | 5% Chrysotile asbestos, (associated mastic is non-ACM per bulk sample results from 2024) | 6 | Good | Manage in place in accordance with the Asbestos O&M Program. Floor tile should be maintained in accordance with EPA and OSHA guidelines. Strip floors when wet using low abrasive pads and low speed buffers (175- 300 rpm), and regularly clean and maintain flooring with wax coating to maximize longevity. Lastly, consider using chair glides to minimize potential for gauging or scratching tile. | |

LF = Linear Feet
SF = Square Feet
NA = Not Applicable

AHERA 3 Year Re-Inspection Summary Table
Riverside School
Summary Table of Identified and Assumed Asbestos-Containing Building Materials
73 Woburn Street, Lowell, MA
Dates of Inspection: 2/22/2024


Assumed ACM = This material was not identified in the Management Plan records and was not sampled during the 2024 Re-inspection. Prior to any planned disturbance by maintenance, renovation, or demolition activities, EFI recommends bulk sampling and analysis to determine asbestos content.

For all recommended response actions, the work should be conducted by a Massachusetts licensed Asbestos Contractor and a work plan for the specific repair or removal activity should be prepared by a Massachusetts licensed Asbestos Designer.

| Physical Assessment Category |
|----------------------------------------------------------------|
| 1 – Damaged or Significantly Damaged Thermal System ACM |
| 2 – Damaged Friable Surfacing ACM |
| 3 – Significantly Damaged Surfacing ACM |
| 4 – Damaged or Significantly Damaged Friable Miscellaneous ACM |
| 5 – ACM with Potential for Damage |
| 6 – ACM with Potential for Significant Damage |
| 7 – Any Remaining friable ACM or friable suspect ACM |

ATTACHMENT B

SITE PLAN AND 2024 REINSPECTION ASBESTOS BULK SAMPLE LOCATION PLANS



EXIT PLAN

14A

| | |
|--|--|
| | |
| | |
| | |
| | |
| | |

16A
16B

01A
02A

| | |
|-----|-----|
| 03A | 06A |
| 03b | 06B |
| 04A | 10A |
| 04B | 10B |
| 05A | 11A |
| 05B | 11B |

MS. SPIEGEL'S
OFFICE

MATH CLASSROOM

ALARM

REAR HALLWAY

Social Studies
CLASSROOM

SPECIAL
PROGRAMING

BATHROOM

KITCHEN

ALARM

HALLWAY

02C
01D
02D
15A

07A
07B

08A
09A
14B
15B

BATHROOM

01B 12A
02B 13B
12A
12B

ELA CLASSROOM

ALARM

FRONT
HALLWAY

SKILLS CLASSROOM

◆ FIRE EXTINGUISHER

FIRST FLOOR

FILE
CABINETS

SCIENCE
CLASSROOM

ALARM

REAR
HALLWAY

08B
09B

01E
02E

RECREATION
ROOM

COUNSELING
OFFICE

01F
02F
01G
02G
15C

MIDDLE
HALLWAY

BATHROOM

2

COMMUNITY ROOM

STEM
CLASSROOM


ALARM

FRONT
HALLWAY

01C

❖ FIRE EXTINGUISHER

SECOND FLOOR



ATTACHMENT C

2024 REINSPECTION ASBESTOS BULK SAMPLE REPORTS



EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com/bostonlab@emsl.com>

EMSL Order: 132401073

Customer ID: EAFI66

Customer PO:

Project ID:

Attention: Derrick Calvario

EFI Global, Inc.

155 West Street

Suite 6

Wilmington, MA 01887

Phone: (978) 688-3736

Fax: (978) 688-5494

Received Date: 02/23/2024 11:50 AM

Analysis Date: 02/27/2024

Collected Date: 02/22/2024

Project: 014.0 - Riverside; 73 Woburn Street; Lowell, MA

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos % Type |
|-----------------------|--------------------------------------------------------------------------|-----------------------------------------|--------------|--------------------------|--------------------|
| | | | % Fibrous | % Non-Fibrous | |
| 01A 132401073-0001 | Social Studies/Science Room - Plaster Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 01B 132401073-0002 | ELA Room 1st Floor - Plaster Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 01C 132401073-0003 | Community Room 1st Floor - Plaster Skim Coat | Tan/White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 01D 132401073-0004 | 1st Floor Hallways - Plaster Skim Coat | Tan/White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 01E 132401073-0005 | 2nd Floor Staircase - Plaster Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 01F 132401073-0006 | 2nd Floor Hallway Left - Plaster Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 01G 132401073-0007 | 2nd Floor Hallway Right - Plaster Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 02A 132401073-0008 | Social Studies/Science Room - Plaster Base Coat | Gray Fibrous Homogeneous | 3% Hair | 97% Non-fibrous (Other) | None Detected |
| 02B 132401073-0009 | ELA Room 1st Floor - Plaster Base Coat | Gray/White Fibrous Homogeneous | 2% Hair | 98% Non-fibrous (Other) | None Detected |
| 02C 132401073-0010 | Community Room 1st Floor - Plaster Base Coat | Gray/White Fibrous Homogeneous | 2% Hair | 98% Non-fibrous (Other) | None Detected |
| 02D 132401073-0011 | 1st Floor Hallways - Plaster Base Coat | Gray Fibrous Homogeneous | 2% Hair | 98% Non-fibrous (Other) | None Detected |
| 02E 132401073-0012 | 2nd Floor Staircase - Plaster Base Coat | Gray Fibrous Homogeneous | 2% Hair | 98% Non-fibrous (Other) | None Detected |
| 02F 132401073-0013 | 2nd Floor Hallway Left - Plaster Base Coat | Gray Non-Fibrous Homogeneous | 2% Hair | 98% Non-fibrous (Other) | None Detected |
| 02G 132401073-0014 | 2nd Floor Hallway Right - Plaster Base Coat | Gray Fibrous Homogeneous | 2% Hair | 98% Non-fibrous (Other) | None Detected |
| 03A 132401073-0015 | Office/Special Programming 1st Floor - 12x12 White Tile w. Flec | Tan Non-Fibrous Homogeneous | | 95% Non-fibrous (Other) | 5% Chrysotile |

Initial report from: 02/29/2024 06:14:58



EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com> / bostonlab@emsl.com

EMSL Order: 132401073

Customer ID: EAFI66

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-----------------------|-----------------------------------------------------------------------------|--------------------------------------|--------------------------------|--------------------------|------------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 03B 132401073-0016 | Office/Special Programming 1st Floor - 12x12 White Tile w. Flec | | | | Positive Stop (Not Analyzed) |
| 04A 132401073-0017 | Office/Special Programming 1st Floor - 12x12 Brown Tile w. Flec | Brown Non-Fibrous Homogeneous | | 95% Non-fibrous (Other) | 5% Chrysotile |
| 04B 132401073-0018 | Office/Special Programming 1st Floor - 12x12 Brown Tile w. Flec | | | | Positive Stop (Not Analyzed) |
| 05A 132401073-0019 | Office/Special Programming 1st Floor - 12x12 Tan Tile w. Flec | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 05B 132401073-0020 | Office/Special Programming 1st Floor - 12x12 Tan Tile w. Flec | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 06A 132401073-0021 | Office/Special Programming 1st Floor - Yellow 12x12 Tile Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 06B 132401073-0022 | Office/Special Programming 1st Floor - Yellow 12x12 Tile Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 07A 132401073-0023 | 1st Floor Bathroom - 1st Floor - Beige 12x12 Floor Tile w. Flec | Beige Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 07B 132401073-0024 | 1st Floor Bathroom - 1st Floor - Beige 12x12 Floor Tile w. Flec | Beige Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 08A 132401073-0025 | 1st Floor BR Off Hallway - 2x4 CT Pinhole | Gray/White Fibrous Homogeneous | 50% Cellulose 35% Min. Wool | 15% Non-fibrous (Other) | None Detected |
| 08B 132401073-0026 | 2nd Floor Rec Room - 2x4 CT Pinhole | Gray/White Fibrous Homogeneous | 50% Cellulose 35% Min. Wool | 15% Non-fibrous (Other) | None Detected |
| 09A 132401073-0027 | 1st Floor BR Off Hallway - 2x4 CT Large Fissure | Gray/White Fibrous Homogeneous | 50% Cellulose 35% Min. Wool | 15% Non-fibrous (Other) | None Detected |
| 09B 132401073-0028 | 2nd Floor Rec Room - 2x4 CT Large Fissure | Gray/White Fibrous Homogeneous | 50% Cellulose 35% Min. Wool | 15% Non-fibrous (Other) | None Detected |
| 10A 132401073-0029 | Office/Special Programming 1st Floor - 12x12 Tile under 12x12 Tile | Brown Non-Fibrous Homogeneous | | 95% Non-fibrous (Other) | 5% Chrysotile |
| 10B 132401073-0030 | Office/Special Programming 1st Floor - 12x12 Tile under 12x12 Tile | | | | Positive Stop (Not Analyzed) |

Initial report from: 02/29/2024 06:14:58



EMSL Analytical, Inc.

5 Constitution Way, Unit A Woburn, MA 01801

Tel/Fax: (781) 933-8411 / (781) 933-8412

<http://www.EMSL.com / bostonlab@emsl.com>

EMSL Order: 132401073

Customer ID: EAFI66

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-----------------------|---------------------------------------------------------------------|---------------------------------------|---------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 11A 132401073-0031 | Office/Special Programming 1st Floor - Assoc. Black Mastic | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 11B 132401073-0032 | Office/Special Programming 1st Floor - Assoc. Black Mastic | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 12A 132401073-0033 | 1st Floor ff ELA Room - Cove Base | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 12B 132401073-0034 | 1st Floor ff ELA Room - Cove Base | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 13A 132401073-0035 | 1st Floor ff ELA Room - Assoc. Yellow Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 13B 132401073-0036 | 1st Floor ff ELA Room - Assoc. Yellow Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 14A 132401073-0037 | 1st Floor Staircase - Gypsum Board | Brown/White Fibrous Homogeneous | 15% Cellulose | 85% Non-fibrous (Other) | None Detected |
| 14B 132401073-0038 | 1st Floor BR Off Hallway - Gypsum Board | Brown/Gray Fibrous Homogeneous | 12% Cellulose | 88% Non-fibrous (Other) | None Detected |
| 15A 132401073-0039 | 1st Floor Hallway - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 15B 132401073-0040 | 1st Floor BR Off Hallway - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 15C 132401073-0041 | 2nd Floor Rear Hallway - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 16A 132401073-0042 | Exterior - White Window Caulk | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 16B 132401073-0043 | Exterior - White Window Caulk | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |

Analyst(s)

John McCarthy (40)

Steve Grise, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-139, VT AL998919, ME LB-0039

Initial report from: 02/29/2024 06:14:58



132401073

BOSTON NORTH

155 West Street | Suite 6 | Wilmington, MA 01887 | PHONE 978.688.3736 | FAX 978.688.5494 | FREE 800.659.1202

BULK SAMPLE CHAIN OF CUSTODY FORM

| | | | | |
|-------------------------------------|------------------------------------------------|---------------------------------------|--------------------------------------------------|-------------------------------------------|
| Report to (Inspector Name): | Derrick Calvario | | Bill To: | Accounts Payable |
| Company: | EFI Global, Inc. | | Address: | Same |
| Address: | 155 West Street | City, State, Zip: | Same | |
| | Suite 6 | Telephone: | 800-659-1202 | |
| City, State, Zip: | Wilmington, MA 01887 | | Email: | US-EFIGlobal-BostonEnviroPC@efiglobal.com |
| Inspector Cell: | 281-825-5012 | | | |
| Project Information | | | | |
| Project No./ Description: | 014.0 - Riverside - 73 Woburn St. Lower, MA | | | |
| Email Report to: | Derrick.Calvario@efiglobal.com | | | |
| Alternate: | | | | |
| Requested Turnaround Time: | | | | |
| <input type="checkbox"/> RUSH (6hr) | <input type="checkbox"/> 1 day (24hr) | <input type="checkbox"/> 2 day (48hr) | <input checked="" type="checkbox"/> 3 day (72hr) | <input type="checkbox"/> 5 day |
| Media and Methodology | | | | |
| Type of Analysis: | PLM | | Check for Positive Stop: | <input checked="" type="checkbox"/> |
| Notes: | Analyze all plaster and joint compound samples | | Date Collected: | 2-22-24 |

| Sample ID | Type of Material | Location |
|-----------|-------------------|-----------------------------|
| 01A | Plaster Skim Coat | Social Studies / Science rm |
| 01B | " " | ELA rm 1st fl |
| 01C | " " | Community / room 1st fl |
| 01D | " " | 1st fl hallways |
| 01E | " " | 2nd fl staircase |
| 01F | " " | 2nd fl hallway left |
| 01G | " " | " " right |
| 02A | Plaster base Coat | Social Studies / Science rm |
| 02B | " " | ELA rm 1st fl |
| 02C | " " | Community rm 1st fl |

Total Number of Samples Submitted: 43

Samplers Name: Derrick Calvario

Samplers Signature

Relinquished By (Client):

Date: 2/23/24 Time: -

Received By (Lab):

Date: Time:



132401073

| Sample ID | Type of Material | Location |
|----------------|-------------------------------------|------------------------------------------------|
| 02D | plaster base Coat | 1st fl hallways |
| 02E | " " | 2nd fl Staircase |
| 02F | " " | 2nd fl hallway left |
| 02G | " " | 2nd fl hallway right |
| 03A | 12x12 white tile w/ fleck | office / special programming ^{1st} fl |
| 03B | " " | " " " |
| 04A | 12x12 brown tile w/ fleck | " " " |
| 04B | " " | " " " |
| 05A | 12x12 tan tile w/ fleck | " " " |
| 05B | " " | " " " |
| 06A | Yellow 12x12 tile mastic | " " " |
| 06B | " " | " " " |
| 07A | Beige 12x12 floor tile w/ fleck | 1st fl bathroom - 2nd fl |
| 07B | " " | " " ↓ |
| 08A | Mastic | " " |
| 08B | " " | " " |
| 08A | 2x4 CT Pinhole | 2nd fl pinhole BR off hallway |
| 08B | " " | 2nd fl rec rm |
| 09A | 2x4 CT large fissure | 1st fl large fissure BR off hallway |
| 09B | " " | 2nd fl rec rm |
| 10A | 12x12 tile under 12x12 tile | office / special programming ^{1st} fl |
| 10B | " " | " " " |
| 11A | associated black mastic | " " " |
| 11B | " " | " " ↓ |
| 12A | Cove base | ^{1st} fl BR off ELA rm |
| 12B | " " | " " " |
| 13A | ^{associated} Yellow mastic | " " " |
| 13B | " " | " " " |
| 14A | Gypsum board | ^{1st} fl Stair Case |
| 14B | " " | ^{1st} fl BR off hallway |

REC'D FEB 23 2024
EMSL-BOSTON

REC'D _____ FEB 23 2024
FMSI-BOSTON

ATTACHMENT D

LICENSES AND TRAINING CERTIFICATES OF ASBESTOS INSPECTOR & MANAGEMENT PLANNER



THE COMMONWEALTH OF MASSACHUSETTS
EXECUTIVE OFFICE OF LABOR AND WORKFORCE DEVELOPMENT
DEPARTMENT OF LABOR STANDARDS

Michael Flanagan
Director

ASBESTOS INSPECTOR

DERRICK W. CALVARIO

Eff.Date: 11/03/2023

Exp.Date: 11/02/2024

AI900703

Member C.O.N.E.S.

WB - NEW

24





This is to certify that

Derrick W. Calvario

39 Valleywood Road, Hopkinton, MA 01748

MA DLS Asbestos Inspector License# AI900703



*has completed requisite training by Video Conference, and has passed an examination for
reaccreditation as:*

Asbestos Inspector Refresher

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location

Zoom Video Conference

Institute for Environmental Education 16 Upton Drive Wilmington, MA 01887

August 3, 2023

Course Dates

23-4811-106-265405

Certificate Number

August 03, 2023

Examination Date

August 03, 2024

Expiration Date

Training Director

16 Upton Drive, Wilmington, MA 01887

Telephone 978.658.5272

www.ieetrains.com

INSTITUTE FOR ENVIRONMENTAL EDUCATION



THE COMMONWEALTH OF MASSACHUSETTS
EXECUTIVE OFFICE OF LABOR AND WORKFORCE DEVELOPMENT
DEPARTMENT OF LABOR STANDARDS

Michael Flanagan
Director

ASBESTOS MANAGEMENT PLANNER

MICHAEL MCCARTER

Eff.Date: 09/08/2023

Exp.Date: 09/07/2024

AP035661

Member C.O.N.E.S.



24



This is to certify that

Michael L McCarter

7 Millstone Road, Windham, NH 03087

MA DLS Asbestos Management Planner License# AP035661



*has completed the requisite training by Video Conference, and has passed an examination for
reaccreditation*

Asbestos Management Planner Refresher

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location

Zoom Video Conference

Institute for Environmental Education 16 Upton Drive Wilmington, MA 01887

April 21, 2023

Course Dates

23-4930-136-219102

Certificate Number

April 21, 2023

Examination Date

April 21, 2024

Expiration Date

Training Director

16 Upton Drive, Wilmington, MA 01887

Telephone 978.658.5272

www.ieetrains.com

INSTITUTE FOR ENVIRONMENTAL EDUCATION